REMONUMENTATION APR 0 6 1995

APR O MMISSION

Arenac

Lot No.

expressed below:

5. Private Claims ___

Arenac County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LISSER #	02詞(40
22 m 2	23	×
350	73	KECOKDED
500	// ယွ	Ž
ALIA VIII	<u> </u>	C
S	7.5	

	Arenac (County)	Located In:	Corner Code ≠	20° & 75
1.	Public Land Survey	T 18N R -4E T R T R	H11	36 PN '94
2.	Property Controlling in Section	T R S T R S T R		
3.	Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Nu

mber

I. Craig W. McVean in a f	ield survey onN	ovember	. 19 94 .
do hereby certify that under requirement			
in lines 1 and 2 above were in confor	mance with regulation	ons and rules therefo	ore as required in the
current manual of survey instructions	of the United States I	Department of the In	terior, Bureau of Land
Management or by a decree of a Court of	of Law and/or that the	corner points mention	oned in lines 3, 4 and 5
above were in conformance with the ru	les of the Michigan B	oard of Land Survey	ors or by a Decree of a
Court of Law established re-estab	lished monumented	re-monumented	recovered found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

H 11 Set 1/4 Section post - J. Burt - 1843. W. Pine 30" S 19° E 20 L. Hemlock 18" N 13° E 9 L.

Arenac County Survey Notes - Post and distance S. to H 13 - 1901. ACRC - Worth Road Plans and Notes - Distance and angle East & West - 1963.

_ , Recorded Plat _

Recorded Survey - L. 1, P. 131 - Found - 1974.

Unrecorded Survey - Harrison Surveys #8105793 - found 3/8" bar with distance and angle ties East and South - 1981.
MDOT ROW Sheet - Show H 11 as found with distance tie East to centerline Highway M 13.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Excavate 2' x 2' hole in centerline Worth Road - Find 3/8" x 18" rebar (Down 2') in line with fence to North and in agreement with ACRC road plans, recorded survey and unrecorded survey and distance tie E. to centerline Highway M-13. Monument accepted as the best available evidence of the position of the original corner.

Reference Pt. "A" - Found LS cap #27595 on iron on S. edge of bituminous of Worth Road. Iron appears to be on a line at a split distance between G 11 and I 11. Monument not in agreement with ACRC plans, recorded and unrecorded surveys or MDOT ROW sheet. Inquiry for information on monument was ignored. Monument was established using improper procedures and is not utilized as H 11-T18N-R4E in this survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H 11 Replace 3/8" rebar with 3" Arenac County brass cap on 5/8" x 24" rebar in mon. box. S 35° W 31.79' (31.3' -R to centerline end CMP) to nail and tag in West end 36" CMP

N 63° E 28.12' to capped 3/8" rebar. S 9° E 47.31' to capped 3/8" rebar.

N 3° E 38.80' to nail and tag in West side 10" Elm.

S 30°02' E 9.85' to Reference Pt. "A".

Date

OF MICHIGAN CRAIG W. **McVEAN PROFESSIONAL** SURVEYOR No. 39098

Signed by Orace	W. M. Ven
Supravor's Michigan Licago	39088