REMONUMENTATION
Corners IAPR 0 6 1995

Arenac County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

LIBER	002 PACE	037
-------	----------	-----

Fo	r corners in 1915	2.	,						
	Arenac COMMIS	Located In:	Corner Code ##			RECORD ARE	Dec 29		
1.	Public Land Survey	T <u>18N</u> R <u>5E</u> T R T R	C 9			LWOOD STATE	<i>l</i> 2 35	RECORDED	
2.	Property Controlling in Section	S T R S T R	Management 1		80	d y	P# 10,1	ED	
3.	Miscellaneous Property in Sec.	S T R S T R		Regi	ster of D	eeds Stam		Number	r
4.	Lat Na E	Recorded Plat			••				
4. 5.		necorded Flat			АВ	CDEF	G H	JK	L M
Ψ.		;			2 6	- 54		 	_ -
					3				
		Forting O			4 - 7			╂—11	12
ا را مام	Craig W. McVean	, in a field survey on July 2 quirements of P.A. 74, Michigan P.A	of 1970, the corner points me	entioned	5	 		++-+	
in	lines 1 and 2 above were in	n conformance with regulations a	nd rules therefore as require	d in the	6 18-	17-16	1/5	╂┉╬╃	—1¦3—
CU	rrent manual of survey instr	uctions of the United States Depa	rtment of the Interior, Bureau	of Land	7			+-+-+	
Ma ah	inagement or by a decree of ove were in conformance wi	a Court of Law and/or that the corn ith the rules of the Michigan Board	of Land Surveyors or by a Dec	, 4 and 5 cree of a	8 19	20 21	-22-	23	—2 4 —
Co	ourt of Law; established,	re-established, monumented, re-	-monumented, recovered, fo	ound as	9	•	+ +	1 1	
-	pressed below:				10 30-	23 -28		26-	—25— 1
N		corners, all in the same town a	and range, may be recorde	ed	"	 		+ + +	 -
	on this certificate				12 -31-	32 33	34-	35	3 ⁶
Α.	Description of original	monument and accessories ar	nd/or subsequent restorati	ion.	13			1	
Λ.	· ·	and the second s	io or outsorquent societat.		•				
	C 9 Set Post - J. Burt - Birch 9" N 52° W 12 L. Do. 9" S 1-1/2° W 19 L.	1843.		•		. · · · · · ·			**
	ties to C 8 and C 10 - G. Arenac County Survey Distance tie to A 9 and D	or Notes - 2" gas pipe 14" 0 9 - 1917. nands Engineering (now Wade-Tri	long -						

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C 9 Found 2" O.D. x 13" long iron pipe in ring of stone with wood stake inside pipe per 1917 County Surveyor Notes at physical centerline of Bordeau Road (E. & W.) and 5' W. of physical centerline of Lentz Road (N & S) Down 1'. Monument accepted as best available evidence of the position of the original corner.

Reference Pt "B" - Found 3/8" rebar - down 0.3' per Edmands Engineering Survey #2399. Notes of job indicated that this rerod was set by doubling the distance South from a found iron at C 8 and found South 1/8 line fence to South of C 8. Monument was established as using improper procedures and is not utilized as C 9-T18N-R5E in this survey.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C 9 Replace 2" pipe with 3" Arenac County brass cap on 5/8" x 24" rebar with 4" plastic sleeve with concrete in a ring of stone down 0.5'.

N 60° W 114.00' to nail and tag in S. side 6" Ash. S 48° W 147.83' to nail and tag in NW, side U.P. N 25° W 30.63' to nail and tag in W. end 60" CMP. \$ 60° E 38.56' to capped 3/8" rebar. N 2° W 6.59' to Reference Pt "B" (3/8" rebar).

OF MICHIGA CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. PROFESSIONA

Surveyor's Michigan License No.

Date