REMONUMENTATION The state of the s APR 0 6 1995

Arenac County Remonumentation

02PAGE 43 LIBER

LAND CORNER RECORDATION CERTIFICATE

For corner 60MM133	Filing Kequir	ement of Act 74, Mich. P.A.	RE O
Arenac (County)	Located In:	Corner Code ##	REC ARENA ARENA
Public Land Survey	T 18N_ R 5E_ T R T R T R	<u>C 11</u>	RECORDED 12 37 FM 19 STEA OF DEEDS
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R		Register of Deeds Stamp & File Number
•	Recorded Plat		
	·		2 6 5 4 3 2
i, Craig W. McVean	_, in a field survey on July 7 equirements of P.A. 74, Michigan P. <i>F</i>		4 7 8 9 10 11 12 ned 6 18 17 16 15 14 13

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

Description of original monument and accessories and/or subsequent restoration: Recorded Surveys - L. 1, P. 285 - Found 3/4" pipe - 1976; L. 1, P. 358 - Found 1" pipe - 1978; L. 1, P. 438-444 - 1981; L. 1, P. 615 - 1987; L. 1, P. 624 - 1989.

13

C 11 Set Post - J Burt - 1843. Lynn 14" S 31-1/2° E 14 L. Hickory 14" N 17° W 67 L.

expressed below:

Arenac County Survey Notes - East Line Section 30 - wood post and distance to C 10 - G.H. Hollister - 1915. Arenac County Survey Notes - Jacobs Drain - 1-1/2" gas pipe 14" long - 1917.

LCRC - L. 1, P. 123 - Found 1" pipe - Sedgeman - 1978.

LCRC - L. 1, P. 159 - Found 3/4" pipe - Mueller - 1981.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C 11 Find 1" O.D. x 2' long iron pipe with nail on S. side - found 3/4" pipe in 1-1/4" O.D. x 2.3' long iron pipe 0.4' to the East of 1" pipe. Excavate found RR spike - down 0.7' under 1" pipe - dig down find 1" pipe bent and meets near bottom of 1-1/4" pipe remove pipes and RR spike, find 3" - 4" diameter wood post per 1915 ACS notes - down 2.0' - use center of wood post as corner. Monument accepted as a careful and falthful perpetuation of the position of the original corner.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 3" Arenac County brass cap on 5/8" x 24" rebar in center of wood post with 4" plastic tile with concrete. N 30° E 47.37' (46.9' -R, 46.98' -R) to set nail and tag in SE. side 12" (8" -R) Apple. S 47° E 32.61' (32.37' -R, 32.35' -R) to set nail and tag in NE. side

South 32.91' (33' -R) to 3/4" pipe.

S 40° W 42,24' to nail and tag in W. side 10" Ash.

\$ 20° E 61.95' to nail and tag in W. side 12" Ash.

S 55° W 49.22' (49.67' -R) to nail and tag #18664 in NW side of dead NE. leaning 10" (8" -R) Cedar.

CEPTED BY THIS ARENAC COUNTY RVEY PEER GROUP AS THE OFFICIAL RNER UNDER MICHIGAN PUBLIC ACT 5 OF 1990 AT A MEETING HELD ON

Signed by Surveyor's Michigan License No.

Date