

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T47-48 NR 33

Benara COUNTY

DESCRIPTION OF CORNER Sec. corner common to sections 2, 3, 34, 35

DESCRIPTION OF CORNER MONUMENT 1" pipe with 4" brass cap

WITNESSES TO CORNER 1-31-59

10" cedar N 60°, W 27 1/2 links. Marked "S34 1/2 P"

14" cedar N 22°, E 32 1/2 links. Marked "S35 1/2 P"

2" cedar S 66°, W 19 links. Marked "S32 1/2 P"

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. Replaced corner from one cedar B. P. bearing S 66°, W 17 links. I. P. down  
and in poor condition. Found two old wood posts in place. Numerous blazes and cruisers  
signatures at corner. Corner lies in swamp.

SURVEYORS SEAL

*Billy D. Buckler*  
SIGNED Billy D. Buckler DATE 4-30-59  
REGISTERED LAND SURVEYOR