Cons. 4047 REV. 10/60

## MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

## LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO NOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

Replaced this corner from one cedar bearing S70°E, 24 lks. Cedar is down and in poor condition. Position fits with other cors. in the area.

SURVEYOR'S SEAL

CIRCLE CORNER RESISTERED .

SIGNED Billy D. Buckles DATE 2/8/67