LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Baraga	Located In:	Corner Code #		
(County)		Comer Code #		
1. Public Land Survey	T 48N R 31W	C2		
2. Property Controlling in Section	S T R R S 24 T 48N R 31W S T R	PCC N. of #16		
3. Miscellaneous Property in Sec.	S T R S T R		Penister of Doods 5	Stamp & File Number
4. Lot No. , Rec 5. Private Claims	corded Plat		1 A B C D E F	and the second s
above were in conformance with r instructions of the United States D a Court of Law and /or that the co	74, Michigan P.A. of 1970, the corner pregulations and rules therefore as require Department of the Interior, Bureau of Law orner points mentioned in lines 3, 4 and	ed in the current manual of survey and Management or by a decree of 5 above were in conformance with	5 6 10 17 16	3 2 1 1 1 2 1 2 1 5 1 5 1 1 4 1 3 -
re-established, monumented, recover	of Land Surveyors or by a Decree ered, found as expressed below: ers, all in the same town and range,	·	8 19 20 21 9 10 30 29 28	3 27 26 25
on this certificate.	ers, an in the same town and range;	may be recorded	11 31 32 33	34 35 36

- A. Description of original monument and accessories and/or subsequent restoration:
- (C2) Quarter corner common to Sections 5 and 6. 1848 Established by Wells Burt, Deputy Surveyor on the Section line between Section corner 40.00 chains south and Section corner on the Township line 39.20 chains north. Set Sugar post. Y.Birch 8 N36E 53 links, Y.Birch 12 S36W 39 links.
- (PCC N. of #16) Intersection of the Easterly N-S 1/16 line of Sec. 24 with the southerly R/W line (50.00 as measured at right angles from the track centerline) of the former DSS&A Railway. Not previously monumented.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (C2) The original post and accessories were not recovered. Found no evidence of the position of the original corner on the ground. Reestablished the corner on the Section line between Section corners 2639.68' south and 2586.88' north, being proportionate to the original record.
- (PCC N. of #16). Monumented the corner on a straight line between monumented 1/16 corner #16, Section 24 and unmonumented 1/16 corner #13, Section 24, at its intersection with the southerly RR R/W line, said intersection being 819.04' north of 1/16 corner #16 as measured along the 1/16 line.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (C2) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 8" Sugar N33E 7.3' mrkd "1/4S NBT" 16" Y.Birch S58E 11.05 do 8" Sugar S15W 11.55' do 11" Sugar N84W 23.3' do Bearings are magnetic. Set sq'd Cedar post adjacent.

(PCC N. of #16) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 6" Balsam N25W 20.55' mrkd "PCC BT" 8" Balsam N54E 16.15' do 9" W.Pine S26E 30.8' do 6" Balsam S23W 9.8'

Bearings are magnetic. Set sq'd Cedar post adjacent.

Surveyor's Michigan License No. 33986 For the Michigan Department of Natural Resources and Environment, Office of Land and

03/25/2010

SZYSZKOSKI LAND

STEPHAN J

IRVEYOR

FORM APPROVED BY MICHIGAN STATE BOARD

16386

16384

d Jan., 1983