## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For comers in

Baraga	Located in:	Corner Code #	
(County)			
1. Public Land Survey	. T <u>48M</u> F T <u>48M</u> F T <u>5</u> F	R 32N G6	• •
Property Controlling     in Section     Miscellaneous     Property in Sec.	S TF S TF S TF		• •


Register of Deeds Stamp & File Number

. Recorded Plat 4. Lot No. 5. Private Claims

Apr 30 1998

19 ر 1 Stephan J. Szyszkoski do hereby state that under \_, in a field survey on \_ requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformence with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



A. Description of original monument and accessories and/or subsequent restoration:
(F6) Center of Section 16. Corner not established in the original survey. Found no subsequent record.

(G6) Quarter corner common to Section 15-16. Corner reestablished in 1975 by Keith L. Sackett by single proportionate measurement between section corners north and south. Set 1° 1.D. x 36° iron pipe with 4° aluminum cap. 13° Sugar N40M 10.7', 6° Sugar S77E 7.0'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner.

(F6) Found no evidence of prior monumentation at the corner position. Established the corner at the intersection of straight lines connecting opposite quarter corners. At the position for the corner I placed a 1"ID x 32" iron pips capped with a 4" dia. cast aluminum HDMR tablet, appropriately stamped. Corner placed and witnessed by B. Wheeler and D. Lampela, Baraga District Office. (66) Recovered the 1975 monument as described, a 1° ID iron pipe capped with a 4° dia. cast aluminum State of Michigan tablet, in good condition, and at record bearing and distance from the 1975 witnesses, both recovered in good condition. Determined the monument to be 0.12' South and 0.57' East of the postition intended in 1975. Accepted the monument as a careful and faithful resstablishment of the position of the original corner. Corner recovered and rewitnessed by D.Lampela and B.Wheeler, Baraga District Office.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner [F6]Set 1° pipe with 4° MONR cap. (66) Found 1° pipe with 4° alua, cap. (F6)Set 1" pipe with 4" MONR cap. Blazed and scribed the following: Blazed and scribed the following: "1/45 NBT" B' Sugar NI4E 12.55' 10" Maple H74H 5.95' "CS 81" The 1975 witnesses: "CS BT" 7" Maple NO6E 15.25" "1/4S NBT" 14" Sugar N3BN 10.7" "CS BT" 4" Spruce 582E 20.5 10" Sugar \$75E 7.0" "1/45 NBT" 12" Maple S09W 36.05" "CS BI" Placed PK nail and washer in E.face Placed a squared maple post adjacent. power pole \$30W 52.0' (slope dist). Bearings are magnetic. Distances to Placed squared post adjacent to cor. notch in lower blaze. Bearings are magnetic. Distances to

STEPHAN J SZYSZKOSKI LAND STIRVEYOR

motch in lower blaze of trees. 339R6 Surveyor's Michigan License No.

6/10/98

For the Michigan Department of Natural Resources - Forest Management Division