LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	60	rne	re	in
гог	LU	ш	13	111

on this certificate.

Baraga (County)	Located In:	Corner Code #					
	T 4011 D 00144	1/0					
1. Public Land Survey	T 48N R 32W T R	<u>K9</u>					
2 Droporty Controlling	s T R						
2. Property Controlling in Section	S 23 T 48N R 32W	13					
	STR						
3. Miscellaneous Property in Sec.	S T R						
, -			Register of	of Deeds Star	np & File	Number	
4. Lot No, Re- 5. Private Claims	corded Plat		A B C	DEF	<u>G н</u>	I J b	C L
J. H. Hace Claims	K9 05/2	20/2010	┇ ┝╸ ┋═┼╴	·∮─ ┼─∳─	 	 	┢┋
ı, Stephan J. Szyszkoski , i		20/2010 do hereby state					12
that under requirements of P.A.	74, Michigan P.A. of 1970, the corner	points mentioned in lines 1 and 2 red in the current manual of survey.	. - -				 -
above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of				17-16-	15	14-	1'3
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, g						24_	
re-established, monumented, recovered, found as expressed below:			1 1 1				

A. Description of original monument and accessories and/or subsequent restoration:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded

(K9) Corner common to Sections 23-24-25-26. 1960 - Remonumented by Neal Sperhake, RLS 7876, in the original position as determined from original B.T. Yellow Birch 18 N33E 11 links. Set 1"IDx36" galvanized iron pipe with aluminum Kimberly-Clark Corp. cap. Maple 9" N64W 39 links, Y.Birch 8" N72E 50 links, Maple 4" S42E 31 links, Y.Birch 7" S60W 54 links. Corner recorded in L2, P91, Baraga County Land Corner Records.

(13-Sec. 23) Southeast 1/16 corner, Section 23. Not established in the original survey.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- (K9) Found the 1960 monument in good condition and at record bearing and distance from two remaining NBTs - the Maples SE and NW are in good condition with overgrown blazes. Accepted the monument as a careful and faithful perpetuation of the position of the original corner.
- (13-Sec. 23) Established the corner at the intersection of straight lines connecting opposite 1/16 corners. The 1/16 corner to the east (corner #14) is that established by the undersigned May 24, 2010 and not that monumented by A.O.Enger in 1971. The position for the corner falls in a timber cuttina.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- (13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. (K9) Fd. 1"ID I.pipe with 4" alum. Kimberly-Clark Set measuring nail with MDNR tag in the side of: Set measuring nail with MDNR tag in: mrkd "1/16S BT" 12" Maple N57E 49.1' 12" Maple N61W 25.65' 1960 NBT 8" Cherry S40E 10.7' do 8" Maple S38E 20.65' do 6" Cherry S45W 24.85' do mrkd "S24 NBT" 7" Sugar N61E 24.45' "S26 NBT" 11" Cedar N57W 55.45' do 12" Sugar S48W 16.35' Sq'd cedar post adjacent. Bearings magnetic. Bearings magnetic. Sq'd cedar post adjacent.

33986 Surveyor's Michigan License No.

08/16/2010 Date

STEPHAN J SZYSZKOSKI LAND

CAND

IRVEYOR

For the Michigan Department of Natural Resources and Environment, Forest Manageme

16467

FORM APPROVED BY MICHIGAN STATE BOAR

14, 1975 sed Jan., 1983 Rervised Oct., 1995

16466