LAND CORNER RECORDATION CERTIFICATE

(County) 1. Public Land Survey 2. Property Controlling in Section S. 3. Miscellaneous S.	T48N R 33N T R T R T R T R T R T R T R T R T R	A10										
(County) 1. Public Land Survey 2. Property Controlling in Section S. Miscellaneous S.	T ^{48N} R 33N T R											
2. Property Controlling S_in Section S_3. Miscellaneous S_	T R	A10										
in Section S_ 3. Miscellaneous S_	TR TR TR											
												
Property in Sec. S_	_ t <u>_</u> k			Re	giste	r of D	eeds	Stan	np &	File	Num	ber
4. Lot No, Recorded 5. Private Claims	Plat		1 °	<u> </u>	3 C	D I	E F	G	H 	ı .	т к	<u>L</u>
	Nov 1	07 1996	3		Ĭ [- ĭ -	Πi		Ĭ			1
Stephan J. Szyszkoski		, 19 do hereby state that unc		L.	_	_ [_	Γĺ	$\prod_{i=1}^{n}$	10-	\Box	\prod	Ţ
requirements of P.A. 74, Michigan P.A.	of 1970, the corner poir	nts mentioned in lines 1 and 2 above were	ln ,			ľ	ΙĪ		_اً_			
		e current manual of survey instructions of tement or by a decree of a Court of Law and	10			Ţ			Ĵ.			
that the corner points mentioned in line	3, 4 and 5 above were a	n conformance with the rules of the Michig	en 🛄			,				Γi	•	-[]-
Board of Land Surveyors or by a De recovered, found as expressed below:	cree of a Court of Law	r, established, re-established, monumento	d, '		9	-20	21		22_	2	3	-2 ₁ 4-
NOTE: Not more than 2 corners, a	in the same town and	range, may be recorded	9		+	-	H	+	╀	H	+	
on this certificate.			10	-3	0 }-	-29	28		2/7	<u>-2</u>	6	-2'5-
			11	-	\dashv	+		\dashv	╁	H	\dashv	+
			12	—3 [°]	1-	-3'2	33		3 4 -	3°	5—	3′6 I
		d/or subsequent restoration: and common to Sections 30 T48N-R33N	13									

Remonumented the corner at the position of the original corner post, and at record bearing and distance from the remains of the two original bearing trees, both recovered. The post was recovered rotted off at ground level but well preserved below ground, in waterlogged sphagnum moss. It is now a 3" dia. spruce post point in excellent condition. The 6" spruce bearing tree is now a 3" wide by 12" long stump fragment with old blaze, overgrowth, axe mark, and bottom of measuring notch plainly visible. The tamarack bearing tree was recovered as a mound of distinctly dark colored organic material surrounded by lighter colored moss. The two adjacent section corners on the range line, both perpetuated original corners, were found to be \$00 deg. 09 min. 25 sec. N, 39.869 ch., and NOO deg. II min. 13 sec. E, 39.810 ch. distant (bearings referenced to astronomic north). At the position of the post, I placed a 1 I.D. x 32" iron pipe, capped with a 4" dia. cast aluminum HDNR tablet, stamped "Michigan Dept. of Matural Resources, 148H R33-34W, 1/4 34/33, PS33986, 11-7-1996".

C. Description of m Placed I ID Iron pipe	conument for corne	r and accessories established to perpetuate locating the position of the corne
aluminum cap. Blazed	and scribed the	•
following new bearing	trees:	
6" spruce N24N 8.6"	"1/45 NBT"	

8" spruce N97E 9.0" "1/4S NBT" 8" spruce \$18E 13.3" "1/45 NBT" B" spruce \$33N 15.1" "1/45 N8T" Placed a 3" squared sugar post adjacent.

Bearings are magnetic.

New bearing trees are marked with a 8K blaze and a lower bla at the root crown. The blazes are scribed as indicated in quotation marks at left, with NBT being on the lower blaze. Distances are horizontal (unless noted) and measured from the corner to the inside of a notch cut into the bottom of the

lower blaze.

For the Michigan Department of Natural Resources - Forest Management Division

SZYSZKOSKI

LAND

SURVEYOR