LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	in
	Baraga	

Baraga		Located In:	Corner Code ≠#	
_	(County)	•		
1.	Public Land Survey	T 48N R 33N	A5	
		T <u>48N R 33N</u>	C5	
		T R		
		T R		
2.	Property Controlling	S T R		
	in Section	S T R	**	
3.	Miscellaneous	S T R		

S ____ R ___

Register of Deeds Stamp & File Number

_ , Recorded Plat _

5. Private Claims

Property in Sec.

i, Staphan J. Szyszkoski , in a field survey on August 26, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(A5) Section corner common to Sections 7-18 T48N-R33M, and 12-13 T48N-R34M. Original corner established in 1846 by U.S. Deputy Surveyor Austin Burt. BTs: Sugar 12 M31 1/4E 21, Sugar 20 M53 1/2M 43. Subsequent BTs established in 1852 during township subdivision: Sugar 18 S68N 27, Ironwood B N67E 21. Found no subsequent record.

(C5) Section corner common to Sections 7-8-17-18. Original corner established in 1852 by U.S. Deputy Surveyor Francis S. Houck. BIS: Cadar 16 M26N 48, Y.Birch 16 S46E 29. Original notes show: 1) north 28.00 ch Top of ridge and ledge 50 C E+N; 2) west 1.22 ch Brook 3 CMMM; 3) south .80 broak 3 C west; 4) south 64.5 top of ridge and ledge 50 C ESE. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner

(AS) Original post and accessories not recovered. Found no acceptable evidence of the position of the original corner. Reastablished the corner by single proportionate measurement to the original record between monumented corners 2632.78' south and 5265.56' north. At the position for the corner I placed a 1"x32" iron pipe capped with a 4" dia. cast aluminum HOWR tablet. A squared post, apparently a forester's approximate corner, was found N498, 18.1' from the monument placed. Several old blazes face the post, as well as an old Celotex location poster with numerous names and dates, and marked "Approx. corner".

(C5) Original post and accessories not recovered. Found no monumentation at the corner position. Although the brook referenced above can be identified to the northwest and southeast of the corner location, it has been obliterated to the south and west by the marshy clearing in which the corner falls. Found no acceptable evidence of the location of the original corner on the ground. Reestablished the corner by double proportionate measurement to the original record between monumented corners 4962.17' west (4964.5 U.S.), 5275.64' north (5280 U.S.), 5285.42' east (5287.9 U.S.), and 5275.64' south (5280 U.S.). From this position, well defined ridges/ledges north and south check with the original record. Recovered a squared post with a Celotex corp. location poster dated 1956 affixed, in a north-south fence line 18' east and 23' north of the corner position. At the position for the corner, I placed a 1'x32' iron pipe capped with a 4" dia, cast aluminum MDKR tablet.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. (C5) Set a 1" pipe with a 4" MONR cap.

(A5) Set a 1" pipe with a 4" MDHR cap. Blazed and scribed the following new Blazed and scribed the following new bearing trees: bearing trees: 13° Sugar SION 3.2' "S13 N8T"

"S18 N8T"

"S7 HBT"

"S7 NBT"

"S12 M8T"

5' Balsan \$45% 9.5' SIS NOT 8 Balsae N32N 15.4 S7 NBT

10" Y. Birch M29£ 35.5" "S8 MBT" 8" Cedar \$34E 59.0' \$17 NBT Placed a 4" squared cedar post, scribed

7-8-17-18, 1' north of the corner.

STEPHAN J SZYSZKOSKI LAND SURVEYOR

10" Sugar with Celotex L.P. MSSE 26.2'

10 Sugar \$10E 18.4'

10" Sugar N87E 23.2"

12" Sugar N33E 19.5'

6" Sugar N44N 16.8"

Surveyor's Michigan License No. .

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14 1975