		RNER RECORDATION CERTIFI			
For corners in	Filing Requirem	ent of Act 74, Mich. P.A. 1970 a	as Amended	1	
Baraga					
(County)	_ Located In:	Corner Code #			
4 6 111 1 16	*** AAU D. TAN				
1. Public Land Survey	T <u>48M</u> R <u>34M</u> T 48M R 34M	A2 A3			
	T R				
	S T R				
2. Property Controlling	S	-			
in Section	S TR				
3. Miscellaneous	S TR S T R	-to-other makes and the state of the state o		Register of Deed Number	is Stamp & File
Property in Sec.	3	enderson commencer to the own statement and the second			
4. Lot No, Reco	orded Plat		1 A B C	DEFG	HIJKL
5. Private Claims			20-6-	─ ┆ ─ ┼─	╶┊╌┼╌┆╌┼╌┆
	Jul	06 2006	3		1-1-1-1
Stephan J. Szyszkoski		, 20 do hereby stat	4 - 7 -	— - -	-10-11-11
		corner points mentioned in lines 1 and		- - - -	+++++
above were in conformance with	h regulations and rules therefo	ore as required in the current manual o	of 6 18	-17- -16- -	-151413
survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in					
conformance with the rules of t	he Michigan Board of Land Sur	veyors or by a Decree of a Court of Law	/; 8 13 19 1	-2021	-222324
established, re-established, mon	umented, recovered, tound as	expressed below:	9	- - - -	
NOTE: Not more than 2 co	orners, all in the same tow	n and range, may be recorded	10-30-	2928	-27-12625
on this certificate.			11		
A Description of original m	onliment and accessories a	nd/or subsequent restoration:	12 - 31	32 33	-34 -35 -30
		Section 1 T48N-R35W. 1959 - Reest	13		
monumented by U.S. Forest Ser	rvice. Set 1° pipe with 4	brass cap. 14" J.Pine S43E 100	links, 8° R.P	ine N71E 76 lin	iks.
(A2) Recovered the 1959 monu	ment in good condition but	od applied in restoring or reestablis with a broken cap, at record bear Could not remove the broken cap so	ing and dista		
with a new monument, describe faithful reestablishment of (A3) Recovered the 1958 monument	ed below. The monument is the position of the origin ment in good condition and overgrown blazes. The oth	3.7' NW of the record proportiona	te position a om the remain	and is accepted sing 1958 NBT R.	as a careful and Pine NE, now 19
		20 j 4 j . j. (6 j . n. 15 j. n. 15 j			
		A Property of			
C. Description of monument (A2) Set 1 "IDX32" I.pipe with MDNR cap. Set measuring nai: 12" J.Pine N60W 14.5' old mai 4" J.Pine N61E 16.1' mrkd 11" J.Pine S56E 36.3' 11" R.Pine S60W 26.2' Set sq'd J.Pine post adjacent are magnetic. Distances are with tag. * denotes 1959 N8	ls in: Dept. o rks vis. * measuri "1/4S NBT" 19" R.P do 6" Maple do 9" W.Bi t. Bearings 6" Maple to nail A metal T. Bearing	s established to perpetuate locating und 1"ID I.pipe with 4" brass MI f Conservation cap. Set ng nails in: ine N69E 49.9' old blazes * 8 N20E 11.7' mrkd "S6 NBT" rch N37N 23.0' old blazes 8 S66N 30.5' mrkd "S12 NBT" sign post is N81N 1.4'. s are magnetic. Distances are to th tag. * denotes 1958 NBT.		* STEPH- SZYSZ * LA SURV N 335	HAN U. KOSKI
Signed by It Shi	1. Insilest	/ .	Date	8/2/0	6

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

Revised May 14, 1975

Revised Jan., 1983

Rervised Oct., 1995 Surveyor's Michigan License No.

Signed by

Date