LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	ıy ı	requirement of Act 14,	WIICH. F.A. 187	· ·		
Baraga	Located In:	Corner Code #				
(County)	Locatod III.	Comer Code #				
1. Public Land Survey	T 49N R 3	2W I13				
aana aana canto ,	T 49N R 3	2W I11				
	TR TR					
2. Property Controlling	S TR					
in Section	S TR					
3. Miscellaneous Property in Sec.	S TR S T R					
Property in Sec.	5 1 K			Register of De	eeds Stamp & I	File Number
4. Lot No, Reco	orded Plat				E F G H 1	IJĸĿ
o. i iivate olaiiis		ov 08 2004		2 6 5	_ A 3 _	_ 2
•		ov 04 2004		3		
, Stephan J. Szyszkoski	_, in a field survey on	, 19 do hereby	state that under	4 7 8-	9——10—	
requirements of P.A. 74, Michig conformance with regulations an	gan P.A. of 1970, the corner p	oints mentioned in lines 1 and	2 above were in	5		
United States Department of the	Interior, Bureau of Land Mana	igement or by a decree of a Cou	irt of Law and /or	6 -18 -17	16-15-	14-13-
that the corner points mentione Board of Land Surveyors or b				7		
recovered, found as expressed b		,	,,	8 19 20	2122	2324-
NOTE: Not more than 2 co	mers, all in the same town a	nd range, may be recorded		9		
on this certificate.				10 30 29	2827	<u>2</u> 5-
				11)
				12 31 32	33-34-	3536- 1
Intersect South Boundary of respectively. Found no othe	er record.					
B. Description of corner ev	vidence found and/or meth	od applied in restoring or re	establishing corn	er:		
(II3) Found the 1969 monumer NBTs and the original Cedar magnetic bearings to the pre The original Cedar BT rec. (III) Found an old 1.5" ID is was not found) 1108' (1133' reasonable accord with the corner. I note that the dissurvey is somewhat defective	BT S70W (measured mag. to evious witnesses and did S70W is still in good continuous pipe with old double R), Corner G11 of record priginal record. Acceptestance I11-I13 is 5375.14	earing N86W) 18 links. I not place too great a wei dition with scribing and blazes and location post 5220' (5254' R) and to a d the 1.5" pipe as the be (82' longer than record)	noted some var ght on the reco notch plainly v er facing. Dis pipe at L11 ap st available ev . My experienc	iance between the rd bearings in re isible. tances north to l prox. 7901' (7939 idence of the pos e in this townshi	record bearin monumenting th ake edge (mean 'R), are all ition of the o	ngs and our ne corner. nder corner in nriginal
C. Description of monumen	at for corner and accessorie	es established to perpetuate	locating the posi	1000	The state of the s	•
(II3) Reset 1969 1"ID I.pi		Drove 1"IDx32" I.pipe wi	th 4"	TITE O	Marie Marie	
alum, cap and made firm with		MDNR cap into fd. 1.5" I leasuring nails in:	D I.pipe.	STEF	HAN J.	4
measuring nails in: 22" Cedar N86W 11.9' origi			S26 NBT"	* SZYS	ZKOSKI	r
12" Cedar \$45W 20.4' scrib	ing plain * 10" o	bl Sugar NO5E 11.9'	do	STEF SZYS L SUR 3	AND X	+ T
18" Cedar S45E 19.5' faces			S35 NBT" 'S34 NBT"	SUN SUN	No. 5	Ž.
Bearings are magnetic. Distantial with tag. * denotes:		gar S85W 19.1' g'd cedar post adjacent.	Bearings	1, 3	3986	ķ
Hall Hith tay. " Genotes .	are i	agnetic. Distances are t	o nail	A	NO SUN	
le 1	10 with	tag		11-1-	COCHTAN.	
Signed by Stepler	1. Smpshost		Date	6/13/03		
Surveyor's Michigan License	No. 3398	6				
						,