LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

	the state of the s			
Baraga	Located In:	Corner Code #		
(County)	·			
1. Public Land Survey	TR TR			
2. Property Controlling in Section	S 32 T 49N R 32W S 32 T 49N R 32W S T R	9 8		
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number	
5. Private Claims I, Stephan J. Szyszkoski , i	n a field survey on 8 12	/04/2008 /11/2008 do hereby state	4 7 1 9 10 1 1 1	L M
above were in conformance with instructions of the United States a Court of Law and /or that the	74, Michigan P.A. of 1970, the corner regulations and rules therefore as requiped pepartment of the Interior, Bureau of corner points mentioned in lines 3, 4 and of Land Surveyors or by a Decreated, found as expressed below:	ired in the current manual of surve Land Management or by a decree o nd 5 above were in conformance with	of 6 18 17 16 15 14	13
NOTE: Not more than 2 corron this certificate.	ners, all in the same town and rang	e, may be recorded	10 30 29 28 27 26 11 12 31 •32 33 34 35	—2'5— ——————————————————————————————————

A. Description of original monument and accessories and/or subsequent restoration:

(9-Sec. 32) East 1/16 corner, Section 32. 1988 - monumented by K.L.Sackett RLS midway and on a straight line between Quarter corner east and Center of Section west. Set 1"IDx36" I.pipe with 4" aluminum MDNR cap. 8" Sugar S83W 10.8', 4" Sugar N01W 11.2', 8" Sugar S74E 10.2'.

(8-Sec. 32) West 1/16 corner, Section 32. 1988 - monumented by K.L.Sackett RLS midway and on a straight line between Quarter corner C12 and Center of Section D12. Set 1"IDx36" I.pipe with 4" aluminum MDNR cap. 6" W.Pine S10W 22.9', 10" Sugar S45E 18.1', 10" Sugar N24E 21.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(9-Sec. 32) Found but did not accept the 1988 monument, the position of which was based on corners D12 and E12 which have been subsequently corrected. Established the corner midway and on a straight line between Center of Setion D12 1303.92' west and Quarter corner E12 1303.92' east, both remonumented by the undersigned. Removed the 1988 monument, which was found N37W 37' distant.

(8-Sec. 32) Found but did not accept the 1988 monument of record. The 1988 position was calculated and monumented in accordance with a position for the Center of Section 32, D12, which was not correct and which has now been remonumented this date. Established the corner midway and on a straight line between C12 1304.21' west and said remonumented Center of Section D12 1304.21' east. Removed the 1988 monument which was found N34W 12.4' distant.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(9) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: mrkd "1/16S BT" 15" Hemlock N78E 6.3' do 6" Spruce S03E 22.6' do 18" Hemlock S45W 18.3' 6" Hemlock NO4W 5.0' do Set sq'd Cedar post adjacent. Bearings are magnetic.

(8) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of: 1988 BT 11" Sugar NO7E 30.3' old blazes do 12" Sugar \$55E 6.9' do 8" W.Pine S45W 16.8' do do 14" W.Pine S25W 23.2' mrkd "1/16S BT" Set sq'd Cedar post adjacent. Bearings are magnetic. The monument leans 0.2' to the west. The center of the cap marks the corner position.

Signed by	Itel	().	Sand	loli.
Surveyor's Mi	ichigan License No.	U	11/2	33986

Date

01/12/2009

SURVEYOR For the Michigan Department of Natural Resources, Office of Land and Facilities FORM APPROVED BY MICHIGAN STATE BOARD

LAND SO 14, 1975 msed Jan., 1983 Rervised Oct., 1995

STEPHAN J

ZYSZKOSKI

16201