MICHIGAN DEPARTMENT OF CONSERVATION

FORESTRY DIVISION

LAND CORNER RECORD

T 49 NR 34 V.

DESCRIPTION OF CORNER Section Corner common to Sections 11,12,13,14 DESCRIPTION OF CORNER MONUMENT_1" Pipe with 4" Brass cap
WITTNESSES TO CORNER _ 6" S. Maple - N 25 T - 12 Links
m . m mm 4.1 Th
14" Thite Pine - N 44 E - 72 Links
8" S. Maple - East - 45 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was found by the Forestry Division Survey crew while making a resurvey of the North half of this Township. Two original B.T.'s in place, badly rotted.

Corner was placed and witnessed Ma y 18, 1950.

SURVEYORS SEAL

SIGNED Len C. Sepalnatu DATE 7/3/51 ...
REGISTERED LAND SURVEYOR