SURVEY & REMONUMENTATION

FEB 2 3 1998

Surveyor's Michigan License No. 39091

LAND CORNER RECORDATION CERTIFICATE Filling Requirement of Act 74, Mich. P.A. 1970

For corners in SECTION	Filing Requi	rement of Act 74, Mich.	P.A. 1970
			RECEIVED FOR RECORD THIS 31S'
Baraga (County)	Located In:	Corner Code #	DAY OF DECEMBER A.D. 1997 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER
1. Public Land Survey	T_50N R_33W T R T R	<u>I-1</u>	RECORDATION RECORDS ON PAGE 813-814
2. Property Controlling S	T R T R T R T R		Relde Bishop BARAGA COUNTY REGISTER OF DEEDS
			Register of Deeds Stamp & File Number
4. Lot No, Recorded	Plat	····	
5. Private Claims I,Michael Mileski, in a that under requirements of P.A. 74, Michael Mileski, in a shore were in conformance with regular survey instructions of the United States decree of a Court of Law and /or that conformance with the rules of the Michael established, re-established, monumented	a field survey on 29 Ji higan P.A. of 1970, the cor ations and rules therefore a Department of the Interior, the corner points mentione gan Board of Land Surveyo	19 97 do hereby ner points mentioned in lines 1 as required in the current man Bureau of Land Management of d in lines 3, 4 and 5 above w rs or by a Decree of a Court o	l and 2 nual of 4 7 8 9 10 11 12 or by a vere in 5 of Law; 6 18 17 16 15 14 13
NOTE: Not more than 2 corners, all on this certificate.	in the same town and r	ange, may be recorded	7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
A. Description of original monumer	nt and accessories and/o	r subsequent restoration:	11 32 33 34 35 36
I-1; Closing Corner common t	o Sections 2 and 3,	T50N, R33W;	
See back of form.	,	, , , , , , , , , , , , , , , , , , , ,	APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County
B. Description of corner evidence	found and/or method ap	plied in restoring or reestab	blishing corner: 10 9-97
I-1; Closing Corner common t			71/
1987. The position of t	this monument was	verified by a traverse.	ting 6" above ground as set by the BLM in I did not remonument the corner, but faithful reestablishment of the position of
C. Description of monument for co	orner and accessories es	tablished to perpetuate loc	ating the position of the corner:
-1; Closing Corner common t			
Found a 2½" aluminum projecting 6" above gro	pipe with a 3" bras und.	s cap stamped as to l	ocation
Set 7" spike SE/side Set 7" spike SW/side Set 7" spike NE/side Set 7" spike SW/side 6" Steel f	8" White Birch 7" Red Maple 6" Sugar Maple 7" Red Maple ence post w/ yellow	\$68°E \$89°W N37°W	35.31' 29.94' 19.80' 19.15' 1.5' MICHAEL
All of the above new be The lower blaze is scribe at the upper blaze were	ed "NBT". Both blaz	ed with upper and lov es and a band around	wer blazes. PROFESSIONAL SURVEYOR No. 39091
		LIBER	4 PAGE 813
11	.	;	

SURVEY & REMONUMENTATION

FEB 2 3 1998

SECTION

- A. Description of original monument and accessories and/or subsequent restoration:
- [→] I-1; Closing Corner common to Sections 2 and 3, T50N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with a cedar post witnessed by a

Fir

S87°E

21 lks.

and a

Cedar

10

S55°W

47 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 13 May 1987 to 4 November 1987 and approved on 24 March 1989, this corner was considered lost and reestablished on line at the proportionate distance between the S½ corner of section 31, T51N, R32W and the SE corner of section 31, T51N, R32W. The BLM monumented this position with a 2½" x 30" aluminum pipe with brass cap and noted the following accessories:

Sugar Maple

S27°E 6

80 lks. (52.80')

Presently alive and 7" in diameter having a partially healed lower blaze with

scribing visible. Set 7" spike

NE/side

Measured

S25°E

52.85

Presently alive and 9" in diameter having a healed lower blaze Set 7" spike SE/side Measured S48°W 7.00

To each of the above BLM new bearing trees, I added an upper blaze. Both blazes and a band around the tree at the upper blaze were painted red.