MICHIGAN DEPARTMENT OF CONSERVATION FORESTRY DIVISION

LAND CORNER RECORD

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR RESTORED.

This corner was replaced from two original W. Pine B.T.'s bearing S60°W 28 links.(has been cut leaving lower half of bottom blaze and notch) N30°E 10 links found stump bottom, badly rotted.

No evidence of use.

CIRCLE CORNER REGISTERED

SURVEYOR'S SEAL

SIGNED Silly & Suckles DATE December 27, 1961

Billy D. Buckler