SURVEY & REMONUMENTATION

APR 2 6 1995

COMMISSION

LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Require	ement of Act 74, Mich.	P.A. 1970							
Baraga (County)	Located In:	Corner Code ##	1	RECEIVED FOR RECORD THIS 19TH DAY OF DECEMBER, A.D. 1994 AT 9:00 A.M						
Public Land Survey	T R T R T R	G-13	AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGES 511-512.							
in Section S 3. Miscellaneous S	_		BARAGA Registe	COU	NTY	REGIS	TER C		•	
4. Lot No , Reco	orded Plat			A B	C E) E F	G Н		K Ł	
	a field survey on		3		5	9	3-	11		2
do hereby certify that under require in lines 1 and 2 above were in collectrent manual of survey instruction. Management or by a decree of a Collabove were in conformance with the Court of Law; established, re-estappressed below:	ments of P.A. 74, Michigan P.A. of informance with regulations and ins of the United States Depart ort of Law and/or that the corner e rules of the Michigan Board of	of 1970, the corner points men d rules therefore as required ment of the Interior, Bureau o r points mentioned in lines 3, 4 f Land Surveyors or by a Decr	ntioned 6 I in the 7 If Land 7 If and 5 If ee of a 6	19-	20	21-		23		3
NOTE: Not more than 4 corns on this certificate.	ers, all in the same town an	d range, may be recorded	11 12 13		32	33	34-	35	- - - -	6-
A. Description of original mon	ument and accessories and	/or subsequent restoration								لببيا
G-13; Section Corne	r common to Sections	33 and 34, T51N, R3	31 W, o n 5 th	ı Co	rrect	ion Li	ne.			
See back of fo	orm.									

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-13; Section Corner common to Sections 33 and 34, T51N, R31W, on 5th Correction Line.

Found 1 1/4" (I.D.) x 30" iron pipe and hemlock post in agreement with Mr. Thompson's new bearing trees the condition of each as described in Part A. This iron pipe is 2.1 feet east of a 10" \pm diameter severely decayed sugar maple stump from which the dim remains of a possible sugar maple stump bears N14°W a distance of 22.4 feet (CL to CL). Set 1" (I.D.) \times 36" galvanized iron pipe with stamped 2" aluminum cap in the center of the stump 2.1 feet west of Mr. Thompson's iron pipe. Accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-13; Section Corner common to Sections 33 and 34, T51N, R31W, on 5th Correction Line.

LIBER

See back of form.

Surveyor's Michigan License No. .

PPROVED LAND CORNER P.A. 345 OF 1990 Baraga County

MICHAEL MILESKI PROFESSIONAL SURVEYOR No. 3909 POFESSION

Signed by 3909<u>1</u>

- A. Description of original monument and accessories and/or subsequent restoration:
 - G-13; Section Corner common to Sections 33 and 34, T51N, R31W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented by a 10" diameter sugar maple witnessed by a

Sugar 10 N15°W 34 lks. (Inconclusive)

The late Norman Thompson, RLS #4348 states in his field notes dated 2 December 1943 (copies of which were obtained from Northern Hardwoods' office in L'Anse) that he set a hemlock post according "to old work there is an old Sug stump looks good". What Mr. Thompson meant by "old work" is not clear. An overall examination of Mr. Thompson's field notes along the fifth correction line for Ranges 30-32 West show that considerable U.S. physical evidence was present. Furthermore, according to timber delineation maps prepared in the 1940's and 1950's and available at Mead's Peshekee Yard office in Champion this area had not yet been logged extensively. I found no other written record of subsequent restoration of this corner other than that of Mr. Thompson's. It is not unlikely therefore that Mr. Thompson's reference to "old work" related to original U.S. evidence. Mr. Thompson noted the following new bearing trees:

Hemlock 12 N20°E 11.0' (Presently alive and 20" in dia. having healed upper and lower face blazes.)

and a

Yellow Birch 7 N66°W 23.2' (Presently alive and 12" in dia. having healed upper and lower face blazes.)

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.
 - G-13; Section Corner common to Sections 33 and 34, T51N, R31W, on 5th Correction Line.

Set 1" (I.D.) x 36" galvanized iron pipe with 2" aluminum cap appropriately stamped as to location as described in Part B.

Set 60d spike	NW/side	9" Sugar Maple	N52°E	26.05
Set 60d spike	SW/side	9" Sugar Maple	S48°E	9.45
Set 60d spike	W/side	5" Sugar Maple	SO1°F	12.70'
Set 60d spike	NE/side	8" Hemlock	N42°W	35.30'

All of the above new bearing trees marked with upper and lower face blazes and scribed "NBT".

Mr. Thompson's new bearing trees as described in Part A were referenced as follows:

Set 60d spike E/side 20" Hemlock N28°E 11.85' Set 60d spike S/side 12" Yellow Birch N65°W 21.40'