Surveyor's Michigan License No. 39091

COMMISSION		RECORDATION CERTI	
For corners in	Filing Requireme	ent of Act 74, Mich. P.A	A. 1970
	ated In:	Corner Code #	RECEIVED FOR RECORD THIS 28TH DAY OF DECEMBER A.D. 1995 AT 10:30 AM
Public Land Survey	T 51N R 32W	I-13	AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION ON PAGES
	T R T R T R		607 - 608. Helda J. lobillard
2. Property Controlling S in Section S	T R T R		BARAGA COUNTY REGISTER OF DEEDS
	T R T R		Register of Deeds Stamp & File Number
4. Lot No, Recorded Pla 5. Private Claims			A B C D E F G H J K L
5. Private Claims			2 6 5 5 7 3
Michael Mileski	Decembe	9:	5 , 5
do hereby certify that under requirements of in lines 1 and 2 above were in conformance manual of survey instructions of the Un Management or by a decree of a Court of L 5 above were in conformance with the rule Decree of a Court of Law; established, re-es as expressed below: NOTE: Not more than 4 corners, all in on this certificate.	with regulations and rules ited States Department aw and/or that the corner of the Michigan Board stablished, monumented,	therefore as required in the coordinate of the Interior, Bureau of points mentioned in lines 3, of Professional Surveyors or re-monumented, recovered,	urrent 7
A. Description of original monument	and accessories and/	or subsequent restoration	13
I-13; Section Corner common			
See back of form.	А	PPROVED LAND CORNER P.A. 345 OF 1990 Baraga County 12-19-95	·
		249	-
B. Description of corner evidence for	und and/or method ap	oplied in restoring or reest	ablishing corner:
I-13; Section Corner common	to Sections 34 a	and 35, T51N, R32W	, on 5th Correction Line.
Found a 1½" dia. iron bearing trees as recordaithful perpetuation of	rded by the BLM	and listed in Part A.	agreement with the local new Accepted as a careful and
C. Description of monument for com	er and accessories es	stablished to perpetuate lo	ocating the position of the corner:
I-13; Section Corner common	to Sections 34 a	nd 35, T51N, R32W	, on 5th Correction Line.
See back of form.			MICHAEL D. MILESKI PROFESSIONAL SURVEYOR No. 39091
Signed by Windel	icalil	Date	28 Dac 1995 MARCHAL

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

TIBER 4 PAGE 697

- A. Description of original monument and accessories and/or subsequent restoration:
 - I-13; Section Corner common to Sections 34 and 35, T51N, R32W, on 5th Correction Line.

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Hemlock 16 N54°E 51 lks. (Recovered as ground level stump remains approximately 20" in dia.)

and a

Hemlock 6 N29°W 58 lks. (Gone)

This corner was recovered by Michael Avery and Stephen Douglas of the Bureau of Land Management during the course of a survey conducted from 17 September 1982 to 30 September 1983 and approved 8 July 1985. According to the field notes of this survey, a 1½" dia. iron pipe projecting 14" above ground was found in agreement with the remains of both U.S. bearing trees. The BLM did not remonument the corner nor record any new bearing trees. However the following local new bearing trees were noted by the BLM:

Sugar Maple 6 N35°E 30 lks. (Set 60d spike NW/side N29°E 19.80')

Sugar Maple 6 S49°W 25 lks.

Basswood 18 N45°W 14 lks. (Set 60d spike SW/side N49°W 9.24')

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - I-13; Section Corner common to Sections 34 and 35, T51N, R32W, on 5th Correction Line.

Replaced found iron pipe with a 1" (I.D.) x 36" galvanized iron pipe with 2" aluminum cap appropriately stamped as to location.

Set 60d spike	N/side	11" Basswood	N75°E	13.23'
Set 60d spike	E/side	10" Red Maple	S05°E	18.52'
Set 60d spike	S/side	12" Sugar Maple	N84°W	20.20'
Set 60d spike	E/side	12" Basswood	W°80N	13.04

All of the above new bearing trees are marked with upper and lower face blazes and scribed "NBT".