SURVEY & REMONUMENTATION

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For	corners	iп

COMMISSION

COMMIS			DECETVE	מחם מי	DECO	שד חכ	ITC 1	CT
Baraga (County)	Located In:	Corner Code #	RECEIVE DAY OF A.M. AN	NOVEME	BER, 1	1996	AT 1	0:30
1. Public Land Survey	T <u>51N</u> R <u>33W</u> T R T R	A-7*	OF LAND RECORDS	CORNE	ER REC	CORDA	TION	
2. Property Controlling S_in Section S_ 3. Miscellaneous S_ Property in Sec. S_	TR TR TR TR		BARAGA Regis		REGI	STER	OF	DEEDS
4. Lot No, Records	ed Plat		A B	C D I	e f g	; н	I J	K L
5. Private Claims			2 6-	5-	4	3-	2 -	1-
that under requirements of P.A. 74, Nabove were in conformance with res	Michigan P.A. of 1970, the co- gulations and rules therefore	as required in the current manual of	4 - 7-	8	9-	10	11-	12
survey instructions of the United Stat decree of a Court of Law and /or th conformance with the rules of the Mi established, re-established, monumen	at the corner points mentions chigan Board of Land Surveyo	ed in lines 3, 4 and 5 above were in ors or by a Decree of a Court of Law;	e	17-	16	15	14	13-
NOTE: Not more than 2 comers, all on this certificate.	in the same town and range	, may be recorded	8 19	20	-21	22	23	24
		•	10 30	29	28	27-	25-	25
A. Description of original monun	nent and accessories and/	or subsequent restoration:	12 -31-	32	33	3'4	35	36
A-7; Section Corner commo	on to Sections 18 and	l 19, T51N, R33W;						_
See back of form.				P	VED LA .A. 345 Baraga	OF 199	90	R
B. Description of corner evidence	ce found and/or method ap	oplied in restoring or reestablishin	g corner:	/	ممرا	1-96)	
A-7; Section Corner commo	on to Sections 18 and	l 19, T51N, R33W;		M				

Found a 5/8" diameter aluminum pipe with a 3½" aluminum cap appropriately stamped as to location as set by the BLM in 1984 at the southeast side of an 8" diameter cedar kingpost having standing fences to the south and west and a down fence to the north. Wired to the southeast side of the kingpost is a very old, square 3" per side, cedar stake approximately 4½ feet tall having scribing on square faces at the top too far gone to read. I did not find the identifiable remains of U.S. bearing trees from this monument. This monument was found to be in agreement with Mr. Crampton's new bearing trees as well as the BLM new bearing tree. Accepted as the best available evidence of the position of the original corner. I did not remonument the corner, but stamped "PA 345 1996" to the cap.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-7; Section Corner common to Sections 18 and 19, T51N, R33W;

Found a 5/8" diameter aluminum pipe with a 3%" aluminum cap appropriately stamped as to location.

Set 7" spike	SE/side	20" Hemlock	N48°E	13.08'
Set 7" spike	NE/side	8" Cedar	S67°E	7.18'
Set 7" spike	NW/side	9" Cedar	S59°W	56.43'
Set 7" spike	NE/side	18" Hemlock	N38°W	13.36'
		Location post	East	1.5'
•		18" Hemlock	N38°W	13.36

Refer to Part A for further description of the above new bearing trees.

* This corner is also M-7 of T51N, R34W.



Signed by Wall	Mules
Surveyor's Michigan License No	39091

Date 31 025 1996

A. Description of original monument and accessories and/or subsequent restoration:

A-7; Section Corner common to Sections 18 and 19, T51N, R33W;

Originally established during U.S. Survey conducted by Austin Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Hemlock

16

S53°W

N45°W

29 lks

14 lks.

and a

Cedar

R

According to a Land Corner Recordation Certificate filed by Robert Crampton, P.S. #24591 and recorded 30 August 1979 in Liber 1 page 350, an "old cedar post found, set a ½" iron bar at intersection of three old fences". Mr. Crampton noted the following new bearing trees:

14" Hemlock N45°E 13.08'
Presently alive and 20" in diameter. I added upper and lower face blazes and scribed the lower blaze "NBT". Set a 7" spike above a small nail and plastic tag marked "RLS 24591" on the SE/side.

Measured

N48°E

13.08

6" Cedar

S85°E

7.18

Presently alive and 8" in diameter. I added upper and lower face blazes and scribed the lower blaze "NBT". No nail and tag found in the tree. Set a 7" spike at the NE/side.

Measured

N67°E

7.18'

12" Hemlock

N45°W

13.36

Presently alive and 18" in diameter. I added upper and lower face blazes and scribed the lower blaze "NBT". Set a 7" spike above a small nail and plastic tag marked "RLS 24591" on the NE/side.

Measured

N38°W

13.36

To all of the above Crampton new bearing trees, I painted the upper and lower blazes red as well as painted a red band around the tree at the upper blaze.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, Mr. Crampton's corner monument was replaced with a 5/8" x 36" aluminum post with cap appropriately stamped as to location. Mr. Douglas states in his field notes that the corner was

"perpetuated by persons unknown, and further perpetuated and recorded by Robert W. Crampton, R.L.S. No. 24591, in 1979, monumented with a cedar post, 3 ins. sq., firmly set, projecting 3½ ft. above the ground, attached to a fence cor. with fences extending N., S. and W., mkd. 18 on NE., 19 on SE., and 13 on NW, weathered faces, alongside is an iron bar, ½ in. diam., firmly set, projecting 6 ins. above the ground, from which a large hemlock stump hole, bears S. 53°W., 29 lks. dist., agreeing with the record position of an original hemlock hearing tree." position of an original hemlock bearing tree.

The BLM noted the following bearing tree:

S62°W

851/2 lks. (56.43')

Presently alive and 9" in diameter having an open lower face blaze with scribing visible. I added an upper blaze and painted both blazes red as well as painted a red band around the tree at the upper blaze. Set a 7" spike on the NW/side. Measured S59°W 56.43'

SURVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION