

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

	MISSION Located In:	Corner Co	.do. #	
Baraga (County)	Located in.	Corner Co		ECEIVED FOR RECORD THIS 30TH DAY
				OF JULY 1996 AT 10:30 A.M. AND
1. Public Land Survey	T <u>51N</u> R <u>33</u>	BW <u>C-5</u>		RECORDED IN LIBER 4 OF LAND CORNER
	T R			ECORDATION RECORDS ON PAGES
	<u>T R</u>			533 ~ 634.
	Ţ R		L L	Belle & Rhilland
Property Controlling in Section	ST R ST R			BARAGA COUNTY REGISTER OF DEEDS
3. Miscellaneous	S T R			
Property in Section	S T R			Register of Deeds Stamp & File Number
	Recorded Plat			A B C D E F G H J K L M
5. Private Claims				
				4-7-8-9-10-11-12
Michael Mileski	_ , in a field survey on	July	19 96	5
do hereby certify that under re	equirements of P.A. 74, Michigan	P.A. of 1970, the come	er points mentioned	6-18-17-16-15-14-13
in lines 1 and 2 above were in	conformance with regulations ar	nd rules therefore as rec	quired in the current	t <u> </u>
	ns of the United States Depa of a Court of Law and/or that the			
5 above were in conformance	e with the rules of the Michigan	Board of Professional	Survevors or by a	
	tablished, re-established, monun	nented, re-monumente	d, rec id, found	
as expressed below:				11
NOTE: Not more than 4 con this certificate.	orners, all in the same town a	and range, may be re	corded	12 31 32 33 33 34 35 36
on this occurrence.				13
A. Description of original	l monument and accessorie	s and/or subsequen	t restoration:	
C. E. Santian Corna	r common to Sections	7 0 17 and 1	9 TE4N D22	ΔΔ <i>I</i> -
O-3, Section Come	1 COMMINION TO OCCUONS	7, 0, 17, and 1	o, 15 m, 135	, v v v,
				APPROVED LAND CORNER
				P.A. 345 OF 1990
See back of form.				Bayaga County
				<u> </u>
				7-10-96
R Description of corner	evidence found and/or met	had samlied in resta	rina or reestablic	hina corner
b. Description of comer	evidence logita and/or mea	nou applied in restor	ing or recordons	ining conton.
C-5: Section Corne	r common to Sections	7 8 17 and 1	8. T51N. R33	w:
,		., .,,	-, ,	· · · ·
				•
Recovered	the BLM monument a	nd all accessori	es as describ	ed in Part A. I could not
conclusively	y verify the condition of	of the U.S. beari	ng trees. I le	ft the BLM monument
in place and	d stamped the cap "P/	A 345 1996". A	Accepted as a	a careful and faithful
perpetuation of the position of the original corner.				
, .	•			
C. Description of monun	nent for corner and accesso	ries established to p	erpetuate locatii	ng the position of the corner:
C-5; Section Corne	r common to Sections	7, 8, 17, and 18	8, T51N, R33	W; WE OF MICHIE
		, ,		6 cm
				* MICHAEL D. * MILESKI
See back o	f form.			PROFESSIONAL &
				SURVEYOR O
				No. 39091
				8
		•		OFESSIONA
	. ///			Control of the last of the las
Signed by	NUN LENE	يكرن	Date \	3 July 1996.
· · · · · · · · · · · · · · · · · · ·				D BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
Surveyor's Michigan Licer	ise No. 39 091	LIBER 4 PAGE	633	REVISED JAN, 1983
		A [() () ()	S. 37 34 E	1,-1,000 1,-1,1

LIBER 4 PAGE 633

A. Description of original monument and accessories and/or subsequent restoration:

C-5; Section Corner common to Sections 7, 8, 17, and 18, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a yellow birch witnessed by a

Yellow Birch 18 S55°E 13 lks. and a Sugar 20 N38°W 45 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was remonumented with a 2½" x 30" aluminum pipe with cap stamped as to location from the remains of both U.S. bearing trees. Specifically, the BLM field notes state that from the monument " a stump hole, bears S55°E, 13 lks. dist. " and " a sugar maple stump, size indeterminate, bears N38°W, 45 lks. dist., with no mks. visible". The BLM noted the following new bearing trees:

Yellow Birch 15 N79°E 38 lks. (25.08')

Presently alive and 17" in dia. having an open lower blaze with scribing visible.

Set 7" spike S/side Measured N74°E 25.08'

Sugar Maple 10 S08°E 49 lks. (32.34')

Presently alive and 15" in dia. having a mostly open lower blaze with scribing visible.

Set 7" spike W/side Measured S08°E 32.34'

Sugar Maple 10 S37°W 46 lks. (30.36')

Presently alive and 13" in dia. having a mostly open lower blaze with scribing visible.

Set 7" spike SE/side Measured S32°W 30.36'

Sugar Maple 13 N42°W 70 lks. (46.20')

Presently alive and 20" in dia. having an open lower blaze with scribing visible.

Set 7" spike SW/side Measured N45°W 46.20'

- C. Description of monument for corner and accessories established to perpetuate locating the position:
 - C-5: Section Corner common to Sections 7, 8, 17, and 18, T51N, R33W;

Found a 2½" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as set by the BLM in 1984.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

17" Yellow Birch N74°E 25.08' Set 7" spike S/side 32.34 S08°E Set 7" spike 15" Sugar Maple W/side Set 7" spike SE/side 13" Sugar Maple \$32°W 30.36 SW/side 20" Sugar Maple Set 7" spike N45°W 46.201

The above BLM new bearing trees were painted red.

SURVEY & REMONUMENTATION

MAY 05 1997

COMMISSION