

MAY 0 5 1997

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For c	 	in

Signed by

Surveyor's Michigan License No. 39091

COMMISSION

For con	Baraga	_ Located In:	Corner Co	de#	RECEIVED FOR	MBER, 1996	AT 10	:30	
1. Pub	(County) lic Land Survey	T <u>51N</u> R <u>3</u> TR_			A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGES 718-719.				
in S	perty Controlling ection cellaneous	T R R S T R R S T R R R R R R R R R R R			BARAGA COUNT	V Me do	etype OF D	と EEDS	
Proj	perty in Sec.	S R			Register of D	eeds Stamp &	File Nun	nber	
5. Priv	Michael Mileski at under requirements of Poove were in conformance y instructions of the United	in a field survey on A. 74, Michigan P.A. o with regulations and ru I States Department of r that the corner points	November , 19 f 1970, the corner points m les therefore as required in the Interior, Bureau of Land mentioned in lines 3, 4 an	9_96_ do hereby hentioned in lines 1 the current manual Management or by d 5 above were in	A B C D 1	E F G H 3 - 10 - 16 - 15 - 15 - 15 - 15 - 15 - 15 - 15	I J K	L N	
conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.					7 8 19 20 9 10 30 29	21 22	23	-24- -25-	
A. De	scription of original mor	nument and accessor	ies and/or subsequent re	storation:	12 31 32	33 34	35	-36-	
D-11;	One-quarter Corner	r common to Sec	tions 29 and 32, T5	51N, R33W;	APPRO\	VED LAND COF			
	See back of form.					A. 345 OF 1990 Baraga County			
B. De	escription of corner evid	ence found and/or m	ethod applied in restorin	g or reestablishin	g corner: 12-	18-96			
D-11;	One-quarter Corner	r common to Sec	tions 29 and 32, T	31N, R33W;					
	Found a railroad sp M-38. I did not ren of the original corn	nonument the co	BLM in 1984. Cor rner. Accepted as a	ner falls 5.0 fe a careful and f	eet north of the aithful reestablis	physical cen shment of th	iterline e posit	of iion	
C. De	escription of monument	for corner and acces	sories established to per	petuate locating	the position of the o	corner:			
D-11;	One-quarter Corner	r common to Sec	tions 29 and 32, T	51N, R33W;					
	Found a railroad s	pike.							
	i) Set 7" spikeii) Set 7" spikeiii) Set 7" spikeiv) Set 7" spike	SE/side SE/side NW/side S/side	Power Pole 8" Sugar Maple 10" Sugar Maple Power Pole	N48°E S32°W S66°W N62°W	98.03' 96.40' 132.59' 141.20'				
	(ii) and (iii) are mar	ked with upper a	are further describe and lower blazes. The and around the tree	ne lower blaze	is scribed laze were	MICHAEL MILESKI PROFESSION	AT SON THE ROLL OF THE PROPERTY OF THE PROPERT		

A. Description of original monument and accessories and/or subsequent restoration:

D-11; One-quarter Corner common to Sections 29 and 32, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a sugar maple post witnessed by a

Sugar

18

N25°W

16 lks.

Sugar

10

N87°E

47 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was considered lost and reestablished midway and on line between government corners immediately to the east and west. The BLM monumented this position with a railroad spike witnessed by a

Power Pole

N49°E

1481/2 lks. (98.01')

Set a 7" spike on the SE/side. Measured

N48°E

Power Pole N58°W Set a 7" spike on the S/side. Massured N62°W

214 lks. (141.24')

98.031

141,201

Each of the above BLM accessories were marked with a vertical red paint stripe.

BUHVEY & REMONUMENTATION

MAY 0 5 1997

COMMISSION