

MAY 0.5 1997 LAND CORNER RECORDATION CERTIFICATE

COMMISSICRITING Requirement of Act 74, Mich. P.A. 1970

For corners in Located in: Corner Code #	THE PERSON THE SOTE DAY
(County)	RECEIVED FOR RECORD THIS 30TH DAY OF JULY 1996 AT 10:30 A.M. AND
- 51N - 22M F-3	RECORDED IN LIBER 4 OF LAND CORNER
1. Public Land Survey T 51N R 33W E-3	RECORDATION RECORDS ON PAGES
T R	649 - 650.
T R	
2. Property Controlling S T R	THE Hilled
in Section S T R	BARAGA COUNTY REGISTER OF DEEDS
3. Miscellaneous S T R	
Property in Section S T R	Register of Deeds Stamp & File Number
· ·	
4. Lot No, Recorded Plat	A B C D E F G H I J K L M
5. Private Claims	
	3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
I, Michael Mileski , in a field survey on July , 19 96	4 7 8 9 10 11 12 -
I, in a field survey on	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the comer points mention lines 1 and 2 above were in conformance with regulations and rules therefore as required in the cu	urrent _
manual of survey instructions of the United States Department of the Interior, Bureau of I	Land /
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4	4 and 8 19 20 21 22 23 24 24
5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or	by a g
Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, for as expressed below:	found 10 30 29 28 27 26 25 -
•	11
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.	$12 \begin{array}{ c c c c c c c c c c c c c c c c c c c$
	13
A. Description of original monument and accessories and/or subsequent restoration:	: APPROVED LAND CORNER
	P.A. 345 OF 1990
E-3; Section Corner common to Sections 4, 5, 8, and 9, T51N, R33	3VV; Baraga County
	180
	7-10-96
Originally established during U.S. Survey conducted by Ha	
1845 and monumented with a sugar maple post witnessed	
Sugar 14 S_W (?) 13 lks. and a Hemlock 1 Continued on back of page	12 N_E (?) 31 lks.
B. Description of corner evidence found and/or method applied in restoring or reesta	ablishing corner:
E-3; Section Corner common to Sections 4, 5, 8, and 9, T51N, R33	
	· · ·
Recovered the BLM monument and all accessories as desc	cribed in Part A. From this
monument a 10" diameter cedar post projecting 5½ feet above ground having a 15" vertical cut scribed as to location bears N35°E a distance of 1.9 feet to center. Also from	
this monument the centerline tangents of Bear Town Road	
west. I left the BLM monument in place and stamped the c	cap "PA 345 1995".
Accepted as a careful and faithful perpetuation of the positi	ion of the original comer.
C. Description of monument for corner and accessories established to perpetuate loc	resting the position of the corner:
	OF MICH.
E-3; Section Corner common to Sections 4, 5, 8, and 9, T51N, R33	MICHAEL D.
See back of form.	PROFESSIONAL SURVEYOR
	39091
· !	APOFESSIONAL
	· · · · · · · · · · · · · · · · · · ·
Signed by Date Date	13 July 1996
Surveyor's Michigan License No. 39091 FORM APP	PROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

A. Description of original monument and accessories and/or subsequent restoration:

E-3; Section Corner common to Sections 4, 5, 8, and 9, T51N, R33W;

According to the field notes of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was remonumented at its original position in 1935 by Marshall J. Hall, Junior Engineer, U.S. Indian Service. The BLM recovered Mr. Hall's field notes of the "Carp River Truck Trail" survey at the Federal Records Center, Chicago, Illinois. The BLM recovered a 2" diameter iron pipe in agreement with Mr. Hall's 1935 bearing accessories. Namely,

Cedar Post, 6" in diameter, scribed as to location on NW face, bears N45°E, 3 lks. dist.

Sugar Maple stump hole N88°E 271/2 lks.

The BLM remonumented the corner with a 2½" x 30" aluminum pipe and cap stamped as to location and noted the following new bearing trees:

Maple N24°E 65 lks. (42.90')

Found sugar maple presently alive and 16" in dia. having a mostly healed lower blaze with some scribing visible.

Set 7" spike W/side N18°E 42.90' Measured

10 lks. (6.60') Yellow Birch 7 S48°E

Presently alive and 10" in dia. having an open lower blaze with scribing visible.

Set 7" spike S/side Measured S52°E

S65°W 91 lks. (60.06') Yellow Birch 10

Presently alive and 15" in dia. having an open lower blaze with scribing visible.

Set 7" spike Measured S60°W 60.06 N/side

N37°W 39 lks. (25.74') Maple 7

Found Sugar Maple presently alive and 9" in dia. having a healed lower blaze.

N44°W 25.74 SW/side Measured Set 7" spike

- C. Description of monument for corner and accessories established to perpetuate locating the position:
 - E-3; Section Corner common to Sections 4, 5, 8, and 9, T51N, R33W;

Found 21/2" dia. aluminum pipe with 3" aluminum cap appropriately stamped as to location as by the BLM in 1984.

13" Sugar Maple S90°E 31.03' Set 7" spike N/side 27.22' 9" Sugar Maple S05°W Set 7" spike W/side **Location Post** N40°E 1.0'

All of the above new bearing trees are marked with upper and lower blazes, scribed "NBT", and painted red.

The following new bearing trees were established by the BLM in 1984. The condition of each is described in Part A.

16" Sugar Maple N18°E 42.90' Set 7" spike W/side S/side 10" Yellow Birch S52°E 6.60 Set 7" spike \$60°W Set 7" spike N/side 15" Yellow Birch 60.06 N44°W 25.74 SW/side 9" Sugar Maple Set 7" spike

REMONUMENTATION

The above BLM new bearing trees were painted red.

MAY 0 5 1997

SURVEY &