

REMONUMENTATION

Signed by

Surveyor's Michigan License No. 39091

LAND CORNER RECORDATION CERTIFICATE

MAY (5 1997) For corners in	Filing Requi	rement of Act 74, Mich.	P.A. 1970	
COUNTY)	Located In:	Corner Code #	DAY OF A.M. AM	D FOR RECORD THIS 20TH DECEMBER, 1996 AT 10:30 D RECORDED IN LIBER 4
1. Public Land Survey	T <u>51N</u> R <u>33W</u> TR TR	G-6	OF LANE RECORDS	CORNER RECORDATION ON PAGES 740-741.
2. Property Controlling S_	TR TR		BARAGA	elda Me Integre
in Section S_ 3. Miscellaneous S_ Property in Sec. S_	TR TR T R		BAKAGA	COUNTY REGISTER OF DEEDS
	· ·		Regist	er of Deeds Stamp & File Number
4. Lot No, Recorded	d Plat			
5. Private Claims				
I, <u>Michael Mileski</u> , in a t	field current on Morrorabe	10 06 1 1	3	5 4 3 2 1
that under requirements of P.A. 74, Mi	ichigan P.A. of 1970, the cor	ner points mentioned in lines 1	y state and 2	8 9 10 11 12
above were in conformance with regu survey instructions of the United State:	lations and rules therefore a s Department of the Interior.	as required in the current man Bureau of Land Management o	nual of	
decree of a Court of Law and /or that conformance with the rules of the Mich	t the corner points mentione	ed in lines 3, 4 and 5 above w	vere in	17-16-15-14-13
established, re-established, monumente	d, recovered, found as expre	essed below:	7 Law;	
NOTE: Not more than 2 corners, all in	n the came town and range	may be recorded	8 19	
on this certificate.	i the same town and range,	may be recorded	9	
			10 30	29 28 27 26 25
A. Description of original monume	ent and accessories and/c	or subsequent restoration:	11	
		·	12 31	32 34 35 36
G-6; One-quarter Corner con	nmon to Sections 15	and 16, T51N, R33W	/; 13 13 13 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
See back of form.				APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County
B. Description of corner evidence	found and/or method ap	plied in restoring or reestab	olishing corner:	Zaraga Courily
G-6; One-quarter Corner com	nmon to Sections 15	and 16, T51N, R33W	/ ;	12-18-46
Found a 2½" diameter aby the BLM in 1984. The corner, but stamped of the position of the or	he position of this m I "PA 345 1996" to	onument was verified	by a traverse.	above the ground as set did not remonument aithful reestablishment
C. Description of monument for co	orner and accessories est	ablished to perpetuate loca	iting the position of	the corner:
G-6; One-quarter Corner com	imon to Sections 15	and 16, T51N, R33W	' ;	SALE OF MICHIGA
Found a 2½" diameter a as to location projecting			mped	* MICHAEL D. *
i) Set 7" spike E	:/side 5" Red M	aple N20°E	39:65'	PROFESSIONAL SURVEYOR O
	N/side 12" Cedai		19.80'	No. 30091
	W/side 4" White	•	72.72'	39091
iv) Set 7" spike N			יבים פיד	
v)	l/side 6" Sugar I Location F		72.83' 1.0'	OFE SSION
v) (i), (iii), and (iv) are mark "NBT". Both blazes as v (ii) is a BLM new bearing	Location F ked with with upper a well as a band around	Post North and lower blazes. The d the tree at the upper	e lower blaze is s	SURVEYOR No. 39091 SPOFESSIONAL Scribed ed red.

A. Description of original monument and accessories and/or subsequent restoration:

G-6; One-quarter Corner common to Sections 15 and 16, T51N, R33W;

Originally established during U.S. Survey conducted by Harvey Mellen, D.S. in 1845 and monumented with a cedar post witnessed by a

Fir 10 N45°E 42 lks. and a Cedar 12 N83°W 12 lks.

During the course of a survey conducted by Stephen Douglas of the Bureau of Land Management from 10 May 1984 to 10 November 1984 and approved 23 September 1985, this corner was considered lost and reestablished midway and on line between government corners immediately to the north and south. The BLM monumented this position with a 2½" x 30" aluminum pipe and cap witnessed by a

Cedar 11 N76°E 30 lks. (19.80')
Presently alive and 12" in diameter having a partially healed lower blaze with scribing visible. Set a 7" spike on the N/side.
Measured N78°E 19.80'

White Pine 5 N38°W 35½ lks. (23.43') Found standing dead.

SURVEY &
REMONUMENTATION

MAY 0 5 1997

COMMISSION