SURVEY & REMONUMENTATION

FEB 2 3 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

	Filing Kednin	Mieur of Act 14, mich.	1 77. 1014
for corners in	-		RECEIVED FOR RECORD THIS 30TH
SECTION		Come Cado #	DAY OF DECEMBER A.D. 1997 AT
Baraga	Located In:	Corner Code #	10:30 A.M. AND RECORDED IN
(County)			LIBER 4 OF LAND CORNER
1. Public Land Survey	T 52N R 33W	A-3*	RECORDATION RECORDS ON PAGE
1. Public Lario Survey			700 000
	T R T R		Relda Bishop
	T R		Tulda Riskop
2. Property Controlling S	R		
	R		BARAGA COUNTY REGISTER OF DEEDS
3. Miscellaneous S	_ T R		
Property in Sec. S	_ TR		Register of Deeds Stamp & File Number
4. Lot No, Recorded Plat			A B C D E F G H I J K L M
5. Private Claims			2 - 6 - 5 - 4 - 3 - 2 - 1 -
I, Michael Mileski, in a fi	eld survey on 10 Nov	ember . 19 97 do here	
shor under requirements of P.A. 74. Mich	inan P.A. of 1970, the cor	DEL DOIUTZ WENTIONEG III IIIIRA	i and 2
shows were in conformance with regula	tions and rules therefore	as required in the curions in	ariua 0: 1 = 1 = 1 = 1
survey instructions of the United States of decree of a Court of Law and for that t	Department of the interior,	Bureau of Land Management of in lines 3. 4 and 5 above	were in 5
conformance with the rules of the Michic	ian Board of Land Survey	Its Ot DA & Decree or a conn	of Law; 6 18 17 16 15 14 13
established, re-established, monumented,	recovered, found as expre	ssed below:	7
			s 19 20 21 22 23 24
A. Description of original monumer	nt and accessories and/	of subsequent restoration	8
_		7 TEOM DOOM	9
A-3; Section Corner common	to Sections 6 and	7, 152N, H33VV;	10-30-29-28-27-26-25
		t d for 34700 mm	B
Originally established du	ring U.S. Survey co	nducted by william	DUIL,
D.S. in 1845 and monur	nented with a woo	d post witnessed by	a 12-31-32-33-34-35-36
Sugar 14 N57°W	12 lks. and a	Sugar 8 N46°E	341ks. 13
During the subdivision o	f T52N, R33W, by	William Burt, D.S. in	1849,
this corner was not rew	tnessed.		
A cruicer's report prepar	ed by Peter Larsen	dated August/Septe	mber 1905 indicates this corner as being
monumented by an "irot	nost set by Shern	nan". No accessorie	s are noted. A corner sketch prepared by
Edward Charles, P.S. #1	2580 nossibly in	1972, indicates the f	following accessories:
Edward Charles, 1.5. #	2000, poodial,		
Tree	N25°10'E	35.901	APPROVED LAND CORNER
	N27°45'E	25.90'	P.A. 345 OF 1990 Baraga County
Fence corner	S49°22'W	29.33'	
Iron pipe on fence line		20.90'	16-9-97
Fence corner	N49°23'W	20.90	THE STATE OF THE S
	و مراه و دو السائل و د	of manument	 ,
Mr. Charles' sketch doe	s not indicate the t	ype or monument.	
	- 50 #405	04	cented a 1" v 24" iron nin. According to a
On 12 April 1973 Arthu	r Enger, P.S. #135	8.) tecovered and ac	cepted a 1" x 24" iron pin. According to a
Land Corner Recordation	n Certificate prepar	ed by Mr. Enger date	ed 28 December 1973 and recorded on 1
August 1974 in Liber 1	on page 123 of the	e Baraga County Lan	d Coulet vecolds, this monditions was
replaced with a 1" (I.D.	x 36" iron pipe w	ith 4" aluminum cap	witnessed by a
PK Nail in fence corner	post N46°W (mag	j.) 20.90°	
and a			
	2 N25°E (mag.	35.90'	
	-	•	
B. Description of corner evidence	found and/or method	applied in restoring or ree	stablishing comer:
A-3; Section Corner common			en e
المراجع والمراجع المراجع	TO SERVE THE SER		
Found # 1" II D 1 v 28"	fron pipe with 4"	aluminum cap 12 inc	thes below the surface. This monument is
in animal at the east add	e of a farm field at	J991 CT Vlatemixoro	Mest of all old felice totalist and an
Lint Mr. Enger's mon	ment in place and	stamped "PA 345 19	397" to the cap. Accepted as the best
available evidence of the	he nosition of the	riginal comer.	
		• •	•
C. Description of monument for	corner and accessories	established to perpetuate	locating the position of the corner:
At management and a second contract the contract of the contra		•	ATTON.

Signed by Surveyor's Michigan Linguage No. 20001

A-3; Section Corner common to Sections 6 and 7, T52N, R33W;

See back of form.

*This corner is also M-3 of T52N, R34W.

LIBER, 4 PAGE 776

Date

MICHAEL MILESKI

ROFESSIONA SURVEYOR

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- A-3; Section Corner common to Sections 6 and 7, T52N, R33W;

Found a 1" (I.D.) iron pipe with 4" aluminum cap 12 inches below the ground.

Set 7" spike	W/side	8" Box Elder	N09°E	73.21'
Set 7" spike	W/side	13" Box Elder	N28°E	29.00
Set 7" spike	N/side	6" Box Elder	S71°E	61.05'
	6' Steel fe	nce post w/ yellow sign	East	10'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

SURVEY & REMONUMENTATION

FEB 2 3 1998

SECTION