## SURVEY & REMONUMENTATION

FEB 2 3 1998

## SECTION

Surveyor's Michigan License No. 39091

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

_		Filing Require	ement of Act 74, Mic	sh. P.A. 1970		
For corners in  Baraga		Located In:	Corner Code #	DAY		7 AT
1. Public Land Surve	y	T <u>52N</u> R <u>33W</u> TR	A-9*	LIBE	30 A. M. AND RECORDED ER 4 OF LAND CORNER ORDATION RECORDS ON P787	
2. Property Controlling	na 5	TR TR TR		14	elde Bishop	
in Section 3. Miscellaneous		TR TR		BAR	MGA COUNTY REGISTER OF DE	ŒDS
Property in Sec.	S	Т К	<del></del>	<u> </u>	Register of Deeds Stamp & File Num	ber
4. Lot No, 5. Private Claims				A	B C D E F G H I J K	T W
I, Michael Milesk that under requirements of above were in conformar survey instructions of the decree of a Court of Law conformance with the rule established, re-established	f P.A. 74, Michiga nce with regulation United States Dep and for that the es of the Michigan	n P.A. of 1970, the corn is and rules therefore a artment of the Interior, I corner points mentioned Board of Land Surveyor	s required in the current Bureau of Land Managem I in lines 3, 4 and 5 abo s or by a Decree of a Co	menual of 4 ent or by a ve were in 5	7 8 9 10 11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	12-
NOTE: Not more than on this certifica		the same town and re	ange, may be recorded	l 8 <u>−</u>	30 29 28 27 26	24
A. Description of original	nal monument a	nd accessories and/or	r subsequent restoration	on: 12	31 - 32 - 33 - 34 - 35	36
A-9; Section Corne	er common to	Sections 19 and	30, T52N, R33W	;	APPROVED LAND CORNER	
See back of t	orm.				P.A. 345 OF 1990 Baraga County	
B. Description of con	ner evidence fou	nd and/or method and	olied in restoring or rea	establishina corner	- 16, 9-97 - 289	
A-9; Section Corne				•		٠
Set a 1" (I.D.	) x 36" galva of trail roads t	nized iron pipe fro o the north, soutl	om Mr. Sackett's i	bearing trees.	This corner is located at the est available evidence of the	
C. Description of mo	nument for corne	er and accessories est	ablished to perpetuate	e locating the posi	ition of the corner:	
A-9; Section Corne	r common to	Sections 19 and	30, T52N, R33W;	;		
Set a 1" (I.D.	) x 36° galva	nized iron pipe wi	ith cap stamped a	s to location.		
Set 7" spike Set 7" spike Set 7" spike Set 7" spike	W/side NW/side NE/side	7" Sugar Maple 8" Sugar Maple 14" Sugar Maple 8" Sugar Maple ce post w/ yellow	9 \$21°E ble \$63°W 9 N36°W	69.67' 82.00' 54.81' 70.73' 20'		
The lower bla at the upper l	ze is scribed blaze were pa	"NBT". Both blaz	ed with upper and res and a band ard	ound the tree	MICHAEL MILESKI PROFESSIONAL SURVEYOR NO. 39091	
		•	LIBER 4	PAGE <b>786</b>	OFFICIAL STATES	
No.	mere	. sell		_	19 1- 1007	
Signed by	-	<u> </u>		Date	, , , , , , , , , , , , , , , , , , ,	

A. Description of original monument and accessories and/or subsequent restoration:

A-9; Section Corner Common to Sections 19 and 30, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Sugar

7

S25°W

and a

Yellow Birch

N77°E

47 lks.

During the subdivision of T52N, R33W, by William Burt, D.S. in 1849, this corner was further witnessed by a

Sugar

30

S52°E

32 lks.

and a

Yellow Birch 12

N77°E

46 lks.

On 22 April 1977, Keith Sackett, P.S. #19006 recovered and accepted a "1½ (in.) I.D. x unknown length iron pipe one foot above ground in line with roads north, south and west. Old blazed line east.". According to a Land Corner Recordation Certificate prepared by Mr. Sackett dated 3 August 1977 and recorded on 20 December 1977 in Volume 1 on page 483 of the Houghton County Land Corner Records, this monument was left in place and the following accessories were established: was left in place and the following accessories were established:

10" Sugar S30°W 32.3'
Presently alive and 12" in diameter having healed upper and lower blazes.
Set 7" spike NW/side Measured S289M 200001

Measured \$28°W

9" Sugar

S82°E

24.2

Presently alive and 12" in diameter having healed upper and lower blazes. Set 7" spike N/side S82°E 24.77'

7" Sugar

N42°W

45.0'

44.4

This bearing tree was logged. The stump was found intact but possibly displaced by machinery.

Measured N42°W

## SURVEY & REMONUMENTATION

FEB 2 3 1998

SECTION