MAR 3 0 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in		•		PEYTETVE	D FOR RE	מאטיני	THIS	25+h	DAY				
	araga (County)	Located In:	Corner Code #	FEBRUAR RECORDE	Y A.D. 2 D IN LIE	2000 A BER 5	T 10: OF L	30 A	.M. ORNE				
1. Public Land	d Survey	T <u>52N</u> R <u>33W</u> T R T R	<u>B-5</u>		TION REX	•		AGE 7	2.				
in Section 3. Miscellane	2. Property Controlling S T R B BARAGA COUNTY REGISTER OF DEEDS 3. Miscellaneous S T R B BARAGA COUNTY REGISTER OF DEEDS Property in Sec. S T R												
4. Lat No.	, Recorded Pla	at		Re	gister of De								
	aims		•	- 1 A 1	B C D E	4	H I						
requirements of conformance wi the United State and /or that the Michigan Board	P.A. 74, Michigan P.A. of ith regulations and rules the so Department of the Interior comer points mentioned in	1970, the corner points me erefore as required in the co or, Bureau of Land Manage lines 3, 4 and 5 above wer by a Decree of a Court	, 19 99 do hereby state the intioned in lines 1 and 2 above arrent manual of survey instruction of the conformance with the rule of Law; established, re-esta	were in tions of 5 of Law s of the 6 1 blished, 7	7 — 8 — • 17 —	9	15-	-11	-12-				
	ore than 2 comers, all in this certificate.	e same town and range, r	may be recorded	8 —1 9 —	9 20	21	22	23	_24_				
A. Description	on of original monument	103	30 29 	28-	27-	26	25						
B-5; One-qu	arter Corner commo	on to Sections 7 and	d 18, T52N, R33W;	12 3	32	33	34	35	_3'6—				
Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with a hemlock post witnessed by a Hemlock 15 N55°W 22 lks. and a Hemlock 10 S18°E 15lks.													
In 1905, P.A. Larsen "set Hem Post 6" in hole of org. ¼ post". Mr. Larsen noted that the northwest U.S. bearing tree was down. He did not note any new accessories.													
A sketch of section 7 prepared by Arthur Enger, P.S. of the Michigan Department of Natural Resources in 1972 indicates this corner as being monumented by a 1" dia. iron pin. Mr. Enger did not note any new accessories.													
B. Descriptio	n of corner evidence for	und and/or method app	lied in restoring or reestabli	ishing corner:									
B-5; One-qu	arter Corner commo	on to Sections 7 and	d 18, T52N, R33W;										
Found a 1¼" x 36" iron rod projecting 15" above ground in a small rock collar in an east-west fence line. A fence also runs to the north. From this iron rod, a severely decayed hemlock stump having no marks bears \$15°E a distance of 10.0 feet which is consistent with the original record. This monument bears N18°51'W a distance of 7.13 feet from the single proportioned position of the corner. Accepted as the best available evidence of the position of the original corner.													
C. Description	on of monument for corr	ner and accessories esta	ablished to perpetuate loca	ting the position	of the corn	er:							
B-5; One-qu	arter Corner commo	on to Sections 7 and	d 18, T52N, R33W;										

Set a 1" (I.D.) x 36" galvanized iron pipe with cap projecting 12 inches above ground.

Set 7" spike	SE/side	18" Red Maple	N27°E	27.14'
Set 7" spike	NE/side	9" Sugar Maple	S58°E	21.97'
Set 7" spike	W/side	8" Sugar Maple	SO4°E	13.37'
Set 7" spike	S/side	11" Sugar Maple	S85°W	34.80'
Set 7" spike	NE/side	8" Sugar Maple	N43°W	18.19'
	6' Steel fenc	East	6.5'	

at the upper blaze were painted red.

LIBER

All of the above new bearing trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree

Surveyor's Michigan License No. 39091 5 PAGE

MICHAEL MILESKI PROFESSIONA SURVEYOR No.

APPROVED LAND CORNER P.A. 345 OF 1990

REVISED MAY 14, 197

REVISED JAN., 1983 REVISED OCT., 1995

Baraga County