REMONUMENTATION

FEB 2 3 1998

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

(Conuty)	Located in:	Corner Code #
Public Land Survey	T 52N R 33W	C-1*
	TR	
	TR	
	TR	
2. Property Controlling	S	·
in Section	S R	
3. Miscellaneous	S R	
Property in Sec.	S TR	

RECEIVED FOR RECORD THIS 30TH DAY OF DECEMBER A.D. 1997 AT 10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGE 794

BARAGA COUNTY REGISTER OF DEEDS
Register of Deeds Stamp & File Number

11

-32

DEFGHIJKLM

E Di Olaima	Recorded Plat
that under requirements of	, in a field survey on <u>28 November</u> , 19 <u>97</u> do hereby state P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2

I, Michael Mileski, in a field survey on 28 November, 19 97 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- A. Description of original monument and accessories and/or subsequent restoration:
- C-1; Section Corner common to Sections 5 and 6, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Yellow Birch 8 N54°W 15 lks. and a Cedar 8 N27°E 14 lks.

During the subdivision of T52N, R33W, by William Burt, D.S. in 1849, this corner was further witnessed by a Yellow Birch 8 S32°W 33 lks. and a Maple 4 S12°E 45 lks.

The north line of section 5 and the north line of section 6 were run by the Michigan Department of Natural Resources in 1977. The field notes of this survey do not mention an existing monument at the corner common to sections 5 and 6.

OF 1990

Corner Co

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-1; Section Corner common to Sections 5 and 6, T52N, R33W;

This corner was considered lost and reestablished on line at the proportionate distance between the northwest corner of section 6 and the north one-quarter corner of section 5. The northwest corner of section 6 was reestablished by double proportionate measure in 1977 by Keith Sackett, P.S. of the Michigan Department of Natural Resources. The north one-quarter corner of section 5 is an original corner perpetuated

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

-C-1; Section Corner common to Sections 5 and 6, T52N, R33W;

by Keith Sackett, P.S. in 1977.

Set a 1"(I.D.) \times 36" galvanized iron pipe with cap stamped as to location projecting 6" above ground.

4" Red Maple 5" Red Maple 13" Aspen 6" Red Maple 13" Aspen 4" Red Maple	N17°E N80°E S64°E S55°W N84°W N54°W	14.15' 33.65' 5.04' 24.15' 9.85' 12.68' 1.5'
	4" Red Maple 5" Red Maple 13" Aspen 6" Red Maple 13" Aspen 4" Red Maple	5" Red Maple N80°E 13" Aspen S64°E 6" Red Maple S55°W 13" Aspen N84°W 4" Red Maple N54°W

MICHAEL
MILESKI
PROFESSIONAL
SURVEYOR
NO.
39091

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

LIBER 4 PAGE 194

*This corner is also C-13 of T53N, R33W.

Date 19 0 ec 1997

urveyor's Michigan License No. 39091