SECTION.		LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970				
For corners in Baraga	Locate		Corner Code #	RECEIVED JANUARY A	FOR RECORD THIS 14TH . D. 1999 AT 10:30 A	. M.
(County) 1. Public Land Survey			G-9		DED IN LIBER 5 OF LA CORDATION RECORDS ON	
2. Property Controlling	T T	_ R _ R _ R _ R		13	lde Biskop	,
in Section 3. Miscellaneous Property in Sec.	S T S T S T	R			DUNTY REGISTER OF DE	
•	,			Regist	er of Deeds Stamp & File Nu	nber
4. Lot No, R 5. Private Claims	ecorded Plat			1 B C	DEFGHIJK	L M
that under requirements of P. above were in conformance survey instructions of the Unidecree of a Court of Law an conformance with the rules of established, re-established, more	A. 74, Michigan P.A. o with regulations and r ted States Department d /or that the corner p f the Michigan Board o pnumented, recovered	of 1970, the corner sules therefore as re- cof the interior, Bur- coints mentioned in the Land Surveyors of found as expressed	equired in the current ma eau of Land Management lines 3, 4 and 5 above v r by a Decree of a Court of I below:	l and 2 4 7 — nual of or by a 5 were in 6 — 10 —	-17 -16 -15 -14	-12-
NOTE: Not more than 2 cor on this certificate.	ners, all in the same to	own and range, ma	y be recorded	9 10 30	29 28 27 26	
A. Description of original	monument and acc	essories and/or si	ibsequent restoration:	11		
G-9; Section Corner of R33W;	ommon to Secti	ons 21, 22, 2	7 and 28, T52N,	12 31	32 33 34 35	36
D.S. in 1849 an Yellow Birch 1 Township Highv NW corner of se 16 August 1909 Bayshore Acres	d monumented 2 N60°E 22 vays Journal, Jo ection 27 and ru 9). This corner i was surveyed b	with a cedar p lks. and a \ hn Markle, Co n east along th s indicated on y Helmuth Ste	unty Surveyor, ind ne section line to th the plat of "Baysh	S81°W 32 lks. licates that a counce L'Anse and Store Acres" recor Mr. Steinhilb ind	On page 66 of the Bar inty road is to begin at a tate line road (entry date ded 18 August 1967. dicates in the description toted.	the ed
B. Description of corner	evidence found and	or method applie	d in restoring or reesta	blishing corner:		
G-9; Section Corner c	ommon to Secti	ons 21, 22, 2	7 and 28, T52N, R	33W; .		
east-west, grade Strongly occupie	ed gravel road (le ed fences run to	lelberg Road). the north and	This monument v to the south. This	vas found 8 inch s monument is c	ysical centerline of an es below the road surfa onsistent with the plat o the original corner.	
C. Description of monum	ent for corner and a	eccessories estab	lished to perpetuate loc	cating the position of	· · ·	
G-9; Section Corner c	ommon to Secti	ons 21, 22, 2	7 and 28, T52N, R	33W;	APPROVE (12 DORF P.A. (15 72 1990 Berega County	1EK
			Ivanized iron pipe thes below the roa		12.17-98 2/12.	
Set 7" spike Set 7" spike Set 7" spike Set 7" spike	SE/side SW/side SE/side SW/side	7" White Spro 19" White Pir 11" White Spro 7" White Spro	e S37°E ruce S44°W	84.21' 87.43' 32.09' 52.36'	MICHAEL * MILESKI * PROFESSIONAL	ļ.

All of the above new bearing trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

6' Steel fence post w/ yellow sign South

20/01 LIBER 5

33.0'

ROFESSION

0.