LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in the second	, 3		RECEIVED FOR RECORD THIS 14TH DAY
Baraga	Located in:	Corner Code #	OF JANUARY A. D. 1999 AT 10:30 A.
(County)			AND RECORDED IN LIBER 5 OF LAND
1. Public Land Survey	T <u>52N</u> R <u>33W</u> T R	<u>G-12</u>	CORNER RECORDATION RECORDS ON PAGE 32.
Property Controlling S in Section S Miscellaneous S Property in Sec. S	TR TRTRTRTRTR		BARAGA COUNTY REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Recorder	d Plat		
5. Private Claims			A B C D E F G H I J K L M 2 6 5 4 3 2 - 1
t, Michael Mileski, ir under requirements of P.A. 74, Michie were in conformance with regulation instructions of the United States Depa Court of Law and /or that the corner the rules of the Michigan Board of re-established, monumented, recovered	gan P.A. of 1970, the corner pass and rules therefore as requirtment of the Interior, Bureau or points mentioned in lines 3, 4 Land Surveyors or by a De	uired in the current manual of survey of Land Management or by a decree of and 5 above were in conformance with	V 5 17 16 15 14 13
NOTE: Not more than 2 corners, all on this certificate.	in the same town and range,	may be recorded	8 19 20 21 22 23 24
A. Description of original monun	nent and accessories and/o	r subsequent restoration:	10 30 29 28 27 26 25
G-12; One-quarter Corner co	ommon to Sections 33	3 and 34, T52N, R33W;	12 31 32 33 34 35 36
D.S. in 1849 and mor Yellow Birch 8 NO This corner is indicate	numented with a cedar 05°W 14 lks. and a ed as the point of begin	Maple 10 S65°E 7 lks nning of the recorded plat of	"The Town of Keweenaw Bay".
8 Description of corner evidence	e found and/or method appl	lied in restoring or reestablishing c	orner:
G-12; One-quarter Corner co	ommon to Sections 33	3 and 34, T52N, R33W;	•


- Found a 1" x 21" square iron rod sharpened at one end at the base of a cedar fence post. Fences run to the north, south and west. This monument fits well with the south line of the plat of Keweenaw Bay. Accepted as the best available evidence of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- G-12; One-quarter Corner common to Sections 33 and 34, T52N, R33W;

Surveyor's Michigan License No. 39091

Replaced found monument with a 1" (I.D.) x 36" galvanized iron pipe with cap stamped as to location and flush with the ground.

Set 7" spike	W/side	7" Sugar	N09°E	36.14 ¹
Set 7" spike	SW/side	11" Sugar	N36°E	90.63'
Set 7" spike	E/side	11" White Pine	S10°W	85.05'
Set 7" spike	SE/side	12" White Pine	S53°W	90:77
-	6' Steel fence post w/ yellow sign		East	0.5'

All of the above new bearing trees were marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.



MICHAEL

MILESKI

PROFESSIONAL

SURVEYOR

No.

39091

RM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971