SURVEY & REMONUMENTATION

FEB 2 3 1998

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

FOI COMERS IN SECTION			
Baraga (County)	Located In:	Carner Code #	RECEIVED FOR RECORD THIS 30TH DAY OF DECEMBER A. D. 1997 AT
1. Public Land Survey	T <u>52N</u> R <u>33W</u> T R T R T R	H-1*	10:30 A.M. AND RECORDED IN LIBER 4 OF LAND CORNER RECORDATION RECORDS ON PAGE
Property Controlling in Section	S TR S TR		Telda Beskop
3. Miscellaneous Property in Sec.	S TR S TR		BARAGA COUNTY REGISTER OF DEEDS Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H I J K L M
	in a field survey on 2 Dec		2 6 5 4 3 - 2 - 1 -
that under requirements of P.A. 7 above were in conformance with	74, Michigan P.A. of 1970, the cor h regulations and rules therefore a States Department of the Interior,	mer points mentioned in lines as required in the current ma	1 and 2 4 7 8 9 10 11 12 anual of
conformance with the rules of th	or that the corner points mentione to Michigan Board of Land Surveyo mented, recovered, found as expre	ors or by a Decree of a Court	were in 6 18 17 16 15 14 13 of Law:
NOTE: Not more than 2 corner	s, all in the same town and range.	may be recorded	8 -19 -20 -21 -22 -23 -24

Originally established during U.S. Survey conducted by William Burt, D.S. in 1845 and monumented with a wood post witnessed by a

Description of original monument and accessories and/or subsequent restoration:

Yellow Birch

on this cartificate.

9 N80°W 20 lks.

and a

Yellow Birch

20 N20°E 42 lks.

APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County

No subsequent record evidence bearing upon the location of this corner was found.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- H-1; North One-quarter Corner Section 3, T52N, R33W;

H-1; North One-quarter Corner Section 3, T52N, R33W;

This corner was considered lost and reestablished midway and on line between the northwest corner of section 3 and the north one-quarter corner of section 2. The northwest corner of section 3 is a probable original U.S. corner. The north one-quarter corner of section 2 is an old fence corner monumented by Edward Charles, P.S. in 1969.

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H-1; North One-quarter Corner Section 3, T52N, R33W;

Set a 1" (I.D.) x 36" galvanized iron pipe and cap stamped as to location projecting 6" above ground.

Set 7" spike	SE/side	13" Red Maple	N29°E	3.09'
Set 7" spike		14" Cedar	S89°E	34.15
Set 7" spike	NE/side	8" Sugar Maple	S35°E	31.17'
Set 7" spike	W/side	13" Sugar Maple	SO2°E	45.891
Set 7" spike	NE/side	12" Cedar	S87°W	0.94'
Set 7" spike	W/side	15" Sugar Maple	N11°W	34.091
	6' Steel fence	post w/ yellow sign	South	1.5'

All of the above new bearing trees are marked with upper and lower blazes. The lower blaze is scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

*This corner is also H-13 of T53N, R33W.

LIBER 4 PAGE 800

