

MAR 3 0 2000

LAND CORNER RECORDATION CERTIFICATE

RECEIVED FOR RECORD THIS 25th FEBRUARY A.D. 2000 AT 10:30 A AND RECORDED IN LIBER 5 OF LA AND RECORDED IN LIBER 5 OF LA CORNER RECORDATION RECORDS ON PAGE 79 and 80	DS
1. Public Land Survey T 52N R 33W 1-4 T R T R T R T R T R T R T R T R T R T R	DS umber
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R 4. Lot No. Recorded Plat 5. Private Claims I, Michael Mileski , in a field survey on July , 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, monumented, recovered, found as expressed below: NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.	umber
4. Lot No, Recorded Plat	
I, Michael Mileski, in a field survey on July, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	K L
I, Michael Mileski, in a field survey on July, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	K 1
I, Michael Mileski, in a field survey on July, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	1 1
I, Michael Mileski , in a field survey on July , 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	1-1-
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.	12-
on the definition.	24
TO 00 20 20 20 20 20 20 20	25
A. Description of original monument and accessories and/or subsequent restoration: 11 12 32 33 34 35	36
I-4; One-quarter Corner common to Sections 10 and 11, T52N, R33W;	<u> </u>
See back of form.	
 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: I-4; One-quarter Corner common to Sections 10 and 11, T52N, R33W; Found a 1¼ " x 38" iron pipe projecting 16" above ground. A 6" diameter cedar corner post with fences to north and east bears S62°W a distance of 1.1 feet. Accepted as the best available evidence of the position the original corner. 	the of
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:	
I-4; One-quarter Corner common to Sections 10 and 11, T52N, R33W;	
Set a 1" (I.D.) x 36" galvanized iron pipe with cap projecting 4" above ground.	
i) Set 7" spike SE/side 8" Cedar N61°E 21.56' ii) Set 7" spike S/side 10" Yellow Birch S73°E 24.23' iii) Set 7" spike N/side 7" Balsam N80°W 22.18' iv) Set 7" spike W/side 8" Red Maple N23°W 12.76' v) 6' Steel fence post w/ yellow sign South 2.0'	
i) and iv) are Crampton new bearing trees and are further described in Part A. ii) and iii) are new bearing trees marked with upper and lower blazes. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red. * MICHAEL PROFESSIONAL SURVEYOR	***
APPROVED LAND CORNER P.A. 345 OF 1990 Baraga County	
15 11: - A d	

Surveyor's Michigan License No. 39091

MAR 3 0 2000

SECTION

A. Description of original monument and accessories and/or subsequent restoration:

\$77°E

N67°W

I-4; One-quarter Corner common to Sections 10 and 11, T52N, R33W;

Originally established during U.S. Survey conducted by William Burt, D.S. in 1849 and monumented with a cedar post witnessed by a

Hemlock

14

and a

Yellow Birch 10

33 lks.

This corner is indicated on a section diagram drawn in a set of field notes taken by Fesing and Flynn dated 24 February 1919. No description of the monument or accessories is given. The distance north to the NE corner of section 10 is noted as 2637.40 feet. The distance south to the SE corner of section 10 is noted as 2645.60 feet.

On the Michigan State Highway Department plans for Federal Aid Project No. 3 Sec. A-2 (File no. R-28-A-2B) approved 26 December 1935, this corner is shown as being 1464.3 feet north of the centerline of U.S. Highway 41. No description of the monument or accessories is given. The distance to the SE corner of section 10 is given as 2646.60 feet.

On the Michigan Department of State Highways plans for State Projects F07013-004 and Ms 07012-006 approved 8 February 1968, this corner is shown as being monumented by a 1½" diameter iron pipe which lies 1453.33 feet north of the centerline of U.S. Highway 41. The distance to the SE corner of section 10 is given as 2646.45 feet. The following accessories are noted:

6" Balsam 9" Poplar 8" Maple

\$80°E \$10°E N20°W

8.36

On 4 March 1994, Robert Crampton, PS #24591 recovered a 11/2" diameter iron pipe. Mr. Crampton noted the following new bearing trees:

6" Cedar

N67°E

21.29

Presently alive and 8" in diameter having a nail and tag set in a partially healed face blaze.

Set a 7" spike

SE/side

Measured N61°E 21.56

I added an upper and lower blaze. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

6" Balsam

S57°E

30.82

Presently alive and 7" in diameter having a nail and tag set in a partially healed face

blaze. Measured

S62°E

30.81' to found nail and tag.

8" Balsam

Presently alive and 10" in diameter having a nail and tag set in a partially healed face blaze.

Measured

N71°W

37.86' to found nail and tag.

6" Maple

N17°W

12.49

Presently alive and 8" in diameter having a nail and tag set in a partially healed face blaze.

Set a 7" spike

W/side

Measured N23°W 12.76

I added an upper and lower blaze. The lower blaze was scribed "NBT". Both blazes and a band around the tree at the upper blaze were painted red.

Refer to Land Corner Recordation Certificate recorded in Liber 4, page 477.