## Survey & REMONUMENTATION

1003

Barry County Remonumentation

May 14 | 1 08 AM '93

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECOIM

## COMMISSION

For corners in

2. Property Controlling

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Sandry	Schondelmarge

			DEMINTED AT AFFAC
Barry (County)	Located in:	Corner Code ##	REGISTER OF DEEDS
Public Land Survey	7 R T R T R	D-6 (C 1/4, 17) Orangeville Twp.	002001

\_\_\_\_R\_ in Section \_\_ T \_\_ \_\_ R \_\_. 3. Miscellaneous S \_\_ Register of Deeds Stamp & File Number \_ R \_ Property in Sec. S

\_\_ , Recorded Plat \_\_ 5. Private Claims \_

T R

John C. Bueche, in a field survey on January 93 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11

Description of original monument and accessories and/or subsequent restoration: D-6 MDNR 1947 Ratekin 10/8 Found iron 3' below surface of road Found MDNR mon. 1.5' deep Set 4" x 60" conc. post with brass E edge of bit. plate 8" above ground PK NW side PP No wit. given; no meas. N or W 1986 Jonker meas. N 2645.40'; W 2635.04'; found R. Moored capped iron

Ratekin 10/82 PK NW side PP S 60° W 96.11'
PK W side 40" Oak S 10° W 90.07'
PK W side 40" Oak N 45° E 32.81' C/L st. sign post N 85° E 12.45' C/L Marsh Rd. W 11.0' On C/L Saddler Rd. West

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

D-6 Found rerod with cap in mon. box On C/L bit. North extended South, C/L bit. N-S, W 11'±
On C/L gravel West C/L 2 track E is N 15'

As per above wit. PP no PK found

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

D-6 Capped rerod in mon. box
Blaze & 40d nail in E side 44" Oak N 45° E 33.55'\* Blaze & 40d nail in E side 12" Ash S 15° E 35.32'
Blaze & 40d nail in SW side 10" Ash S 40° E 27.23' Blaze & 40d nail in S side 18" Oak S 75° E 32.75' Blaze & 40d nail in NW side PP S 60° W 95.75' PK W side 44" Oak N 45° E 32.81'\* (same tree) PK W side 44" Oak S 10° W 90.07' C/L bit. W 11'± Meas. by hand

Bueche

Date 1-27-93

MANAGO LAND

Surveyor's Mighigan License No. \_\_\_

13027

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

OF MICHIGAN

JOHN C BUECHE LAND SURVEYOR