STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORT

Barry County Remonumentation

May 14 11 08 AM '93

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Sandy Schondelmayer REGISTER OF DEEDS

corners	

Barry		Located in:	Corner Code ##
	(County)		
1.	Public Land Survey	T R T R	Orangeville Tw
		T R	
		T R	1-14
2.	Property Controlling	S T R	
	in Section	S	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

002005

Register of Deeds Stamp & File Number

___ , Recorded Plat ___ 4. Lot No. 5. Private Claims

John C. Bueche in a field survey on 93 January , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

	• •		·	-	-	*						
2		6—		5—	L.	4_	L,	3		2		
3		<u> </u>							_	<u> </u>		
4	L	ļ 7—	_	 8—	L,	ļ —	L.,	.	1	1	<u> </u>	 2—
5		ـــ		4	-			ļ	_			
6	<u> </u>	8-	<u> </u>	 7—	L ₁	6—	1	 5	1	4	1	3—
7		_		_								
8	L_1	9	2	0	2	1	<u>2</u>	2	<u></u> 2	3	<u>2</u>	4
9	<u> </u>	<u> </u>					_					
10	3	 	2	9	2	8	<u>2</u>	7	2	6	2	5
11	<u> </u>	ļ										
12		 	3	2	<u></u> 3	3—	—з	ļ	<u></u> 3	5	3	6
13												

A. Description of original monument and accessories and/or subsequent restoration:

E-5 MDNR 1947 Found iron pipe & 2" x 2" stake @ intersection of fences Set 4" x 60" conc. post with brass plat 8" above ground No wit. given

LCRC #373, Sept., 1984 DNR conc. mon. with brass cap Nail in S side PP N 60° W 58.66' Nail in N side 14" Oak S 50° W 14.67' Nail in SW side 24" Oak S 30° E 42.91' E-W power line N 27'+

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-5 Found MDNR mon. dated 1947

As per above wit. 14" Oak gone

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-5 MDNR mon. dated 1947

Set 40d nail over existing nail in S side PP (#124 on E side of pole) N 60° W 58.70'

Blaze & 40d nail in SW side 24" Oak S 30° E 42.55'

Blaze & 40d nail in E side 14" Oak S 10° W 32.70'

Blaze & 40d nail in N side 8" Oak S 65° W 45.73'
Blaze & 40d nail in E side 14" W. Cherry N 15° E 80.22'

On old fence South; E-W power line N 27'±

Meas. by hand

C Bucke

_ Date .

LAND

VEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 FORM APPROVED BY MICHIGAN STATE

JOHN C

BUECHE LAND SURVEYOR

13027

Surveyor's Michigan License No.

13027