FEB 1 7 1998

SECTION

Barry County Remonumentation

LAND CORNER RECORDATION CERTIFICATE

or comers in	n	Filing Requireme	ent of Act 74, Micl	h. P.A. 1970		
Barry	County)	Located In:	Corner Code ##			
Public La	nd Survey	' K	J-6 (Center 14) Hastings Twp.			
Property (in Section Miscellan Property i	n S eous S		Sandy Sohor	ndelmayer - Barry Registe	Co. LCRCR or of Deeds Stamp	2622 Page: 1 of 10/20/1997 01:0
Lot No.	Reco	rded Plat				
Private CI	aims	rded Plat			ABCDEF	GHIJK
		t .		3	5 1	1-3-1-2-1
Steven Ko		August 31 a field survey on		96 4	_ }	
ourt of Law; pressed belo OTTE: Not n on th	established, re-est ow: nore than 4 corne is certificate.	rules of the Michigan Board of Lan ablished, monumented, re-monu rs, all in the same town and ra	mented, recovered, t	ound as 10 10 11 12 13	30 29 28	27 26 34 35
Description	on of original mone	ument and accessories and/or	subsequent restorat			-
J-6 Come	r not set by GLO	1. Wilson 1867 Stone & brick Beech 14, N68 1/2W 64	2. Bowen Dec. 24, Set Stone & Brick Beech 14 N68 1/2V	at intersection of	3. Seth Pro 1/4 lines same w	
Descriptio	on of corner evider	ice found and/or method applie	ed in restoring or re	establishing com	ner:	
J-6 F6 A	ound bricks and cre accepted found bric	ockery pieces as the monument r ks and crockery as best evidence	epresenting the corn of historical position	er. n.		
		·		PPROVED BY PEER	COUNTY REMONUN REVIEW AT A MEET 1996 COUNT	ientation ing held on > Ty surveyor
Bescrintin	n of monument for	corner and accessories estab	lished to pernetuate	e location the no-	sition of the corne	r:
•		Co. Mon. (3/4" x 24" Iron Rod v		ooming the po-	Julion of the Collic	
S	et spike & Barry C et spike & Barry C	o. Remon. tag in N side 24" Maj o. Remon. tag in S side 14" Ash	ple S80W N70°W	24.31' 21.33'	hitely high house	OF MICHIGAN

Set spike & Barry Co. Remon. tag in W side 18" Oak Set spike & Barry Co. Remon tag in W side 8" Birch N5°W S25W 37,96 28.05° 81.7° NE corner metal cattle shed N40E Tree line to East 3' North



. 0		of the party of the same of th
Signed by	Kel-	Date 6-13-1997
Surveyor's Michigan License No.	39085	The second secon