## SURVEY & REMONUMENTATION

APR 2 6 1995

or corners in

Lot No. \_\_\_ Private Claims

BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Nov 22 3 43 PM '94

STATE OF THOMPAN COUNTY OF BARRY RESTAIL TOUTOR

COMMISSION	١	ì
------------	---	---

Filing Requirement of Act 74, Mich. P.A. 1970 Rutland Township

Barry	Located In:	Corner Code ++						
(County)	·							
Public Land Survey	T <u>3N</u> R <u>9W</u> T R	M-10 E 1/4 Corner						
	T R	Section 25						
	T R							
Property Controlling	S T R							
in Section	S T R							
Miscellaneous	S R							
Property in Sec.	S T R							

\_\_ , Recorded Plat \_\_

Sandy Columbelance jus REGISTER OF DEEDS

002243

Register of Deeds Stamp & File Number

Chris Marschall , in a field survey on \_ , 19 \_94\_ August 8 hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned ines 1 and 2 above were in conformance with regulations and rules therefore as required in the irrent manual of survey instructions of the United States Department of the Interior, Bureau of Land anagement or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 pove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

pressed below: OTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

ourt of Law; established, re-established, monumented, re-monumented, recovered, found as

GLO Set Stake @ 40	Ch.	Beech 20	S77W 50
•		Beech 16	N57W 39
Stone and Brick	No Da	te	
6" Butternut	s73W	20.5	
<u>7" Elm</u>	N13E	40 <b>'</b>	
20" Beech	s77W	50'	
16" Beech	N57W	39'	

	Α	В	С	Ø	E	F	G	н	. 1	J	K	L	M	ŧ
2	L	[ 6—		5—	lacksquare	4		3—		- 2 -	$\downarrow$	 1	_	
3	<u> </u>	<u> </u>	<u> </u>	_	1		_	$\perp$	<u> </u>	ŀ	4			l
4	$\vdash$	ļ 7—	L	8—	<u> </u>	ļ 9 —	ļ.,	 -10	1_	 -11-	4	1	2—	l
5	<u> </u>		_	_	_	1	$\downarrow$	<u> </u>	ļ	$\perp$	_			
6	-	 18	-	 17	┞	 1 <del>6</del>	1	15	Ŀ	 -14-	1	_   1	з—	l
7	_	_	L		_	-	<b> </b>	<u> </u>		1.				ı
8	<u> </u> -	 19—	L	20—	<del> </del>	 21—	╁_	 -22—	1	-23-	$\downarrow$	_2	4—	
9	╙	<del> </del> _	<u> </u>	ļ	ļ	<del> </del>	1	_	L	$\perp$				ļ
10	-	] 30—	L	 29—	<del> </del>	 28—	╀	27—		-26-	_	_2	5-4	þ
11	$\perp$	1	┡	igspace	┡	╄	╄	$\perp$	╙	4	4	•		ļ
12	-	 3 1	-	 3 <b>2</b> -	<del> </del>	 33	+	34	<u> </u>	 35-	+	-3	6	1
13		1	I	1		1	1	1		ĺ				ı

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found Nothing down to 5 feet Set Standard Barry County Monument Midway and on line between NE and SE corner of Section 25

> ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON

7 June

**BRIAN REYNOLDS** 

COUNTY SURVEYOR

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-11 Standard Barry County Monument (3/4" Iron) with Aluminum Cap. Nail and Tag in SW side Twin 8"-12" Oak 72.64' Nail and Tag in W side Twin 10" Oak N25°E 63.02' N85°E Nail and Tag in S side Twin 34" Butternut 25.371 Sl0°W Nail and Tag in W side PP 98.55' Intersection of Hall and Cook Roads 175'± North



urveyor's Michigan License No. \_\_\_\_

\_\_\_\_\_\_Date \_\_\_August 8, 1994