SURVEY & REMONUMENTATION

APR 2 6 1995

Barry County Remonumentation

DEC 8 8 36 AM '94

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECOUR

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

or corners in		•	Sandry Schandelmaryer
Barry	Located In:	Corner Code ##	REGISTER OF DEEDS
(County)	2004100	0011.0. 0000	REGISTER OF DECOS
Public Land Survey		I-13 (SE, 34) Yankee Springs Twp.	002257
Property Controlling	S T R		
in Section			
Miscellaneous Property in Sec.	S T R	Re	egister of Deeds Stamp & File Numbe
Property in Sec.	<u> </u>		•
Lot No , Re	ecorded Plat		— АВС D Е F G H } J K
Private Claims			
			2 - 6 - 5 - 4 - 3 - 2 - 3
			3
Tohn C Bucche	Contomb	or 94	4 - 7 8 9 10 11 1
	in a field survey on <u>Septemb</u> uirements of P.A. 74, Michigan P.A. of 19		5
- · ·	conformance with regulations and rul		6 18 17 16 15 14
	ctions of the United States Department		7
	Court of Law and/or that the corner point		8 19 20 21 22 23
	the rules of the Michigan Board of Lan		9
urt of Law; established, re pressed below:	e-established, monumented, re-monu	mented, recovered, tound as	10 30 39 39 37 36
	arrays all in the same town and re	ange may be recorded	11
on this certificate.	rners, all in the same town and ra	inge, may be recorded	12 31 32 33 34 35
on ans cerancate.			13 1 32 33 34 35
Description of original m	nonument and accessories and/or	subsequent restoration:	13 1
I-13 GLO	· ·		
W. Oak 14" N 6	85° E 50 11rc	what was there	omm., does not state
W. Oak 8" N 81		26" R. Oak N 71	, 1900 * w 41 sł
w. Cak o N or	T W OO IKS.	48" B. Oak N 21'	
Bowen, 1875		40 B. Oak N 21	£ 20.3
Stone		LCRC #191, Jan.,	1076
	53° E 52 lks.(34.32')) 1 $1/2$ " solid ire	
	0° E 100 lks.(66')	S 36° E 24.20' 8	
,, Call 0 11 10	2	S 21° W 19.38'	
		N 87° W 42.75'	32" Oak
Description of corner ev	idence found and/or method appli	ed in restoring or reestablishin	g corner:
which checks Found 1 1/2" p Found 1 1/2" p	rge stone 10" dia. x ALLEN'S ACRES SUB., pipe 12' <u>+</u> South & 11' pipe 11' <u>+</u> South & 4' <u>+</u> ed as a careful and f	recorded in Feb., ' <u>+</u> West, LCRC #191 <u>+</u> West	1962
of the origin		.a.contar betherdrag	can of the position
or the otisti	ial Corner.	ACT 3/15 RADDY O	OUNTY REMONUMENTATION
			EVIEW AT A MEETING HELD ON
		ATTIONED DET LEIN IN	
		<u> Br</u>	DEC 6, 1991
		BRIAN REYNOLDS	COUNTY SURVEYOR

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I-13 Replaced stone with Barry Co. Mon. (3/4" x 24" Pin with Cap)
on top 3/4" x 24" Pin
Nail & Barry Co. Remon. Tag in N side 24" Oak N 90° E 59.44'
Nail & Barry Co. Remon. Tag in NW side 14" Oak N 60° E 33.78'
Nail & Barry Co. Remon. Tag in E side 10" Oak S 25° E 55.67'
Nail & Barry Co. Remon. Tag in W side 12" Oak S 25° W 48.33'
Nail & Barry Co. Remon. Tag in E side 6" Oak S 55° W 66.50'
N edge of 2 track E-W, South 12'+
C/L bit. (Yankee Springs Rd.) West 520'±
1 1/2" pipe 12'± South & 11'± West
1 1/2" pipe 11' ± South & 4' ± West
A D D D D D D D D D D D D D D D D D D D

John C. Bueche ⊒rveyor's Michigan License No.

14a. IGAN STAPQAAR RVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983