BARRY COUNTY REMONUMENTATION LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

2 04 PM '94 Oct 17

Sandry	School	almaryer
REGIS	TER OF	DEEDS

For corners in				·		Sandry Schondalmaryer
1. Public Land Survey CARLTON TOWNSHIP		Located In:		Corner Code ## A-6		REGISTER OF DEEDS
		т <u>4N</u> R <mark>8W</mark>			002234	
W 1/4 COR SEC 18			_ R	,		
 Property Controlling in Section Miscellaneous Property in Sec. 	s s	T T	_ R _ R _ R		Regi	gister of Deeds Stamp & File Number
4. Lot No, 5. Private Claims, BRIAN REYNOLDS	•					A B C D E F G H J K L 2 6 5 4 3 2 3 4 7 8 9 10 11 12-5
do hereby certify that under rein lines 1 and 2 above were current manual of survey inst Management or by a decree of above were in conformance with Court of Law; established, expressed below:	equirement in conform ructions of f a Court of vith the rule	is of P.A. 74, nance with it I the United Law and/or es of the Mic	Michigan P.A. regulations an States Departimat the cornecting an Board of the Cornecting and Board of the Cornecti	of 1970, the corner points me id rules therefore as require tment of the Interior, Bureau er points mentioned in lines 3 of Land Surveyors or by a Dec	entioned of in the of Land , 4 and 5 cree of a	6 13 17 16 15 14 13 7 8 19 20 21 22 23 24 9 10 30 29 28 27 26 25
NOTE: Not more than 4 on this certificate		all in the s	ame town ar	nd range, may be recorde	ed	11 12 31 32 33 34 35 36

- Description of original monument and accessories and/or subsequent restoration:
- NOT SET BY GENERAL LAND OFFICE. NO HISTORICAL DATA OF RECORD COULD BE FOUND FOR THIS CORNER.
- 2. SURVEY OF SECTION 18, c. 1992, BY BURT WICKHAM, P.S. #17639, PRIVATE NOTES READ, "SET 1/2" RE-ROD ON LINE BETWEEN NE CORNER SECTION 13-4N-9W (BRANT CAPPED IRON) AND E 1/4 CORNER SECTION 13-4N-9W (NEDERVELD CAPPED IRON) EQUIDISTANT FROM NW CORNER SECTION 18-4N-8W (BRANT CAPPED IRON) AND FENCE LINE RUNNING EAST AT SW CORNER OF SECTION 18-4N-8W"
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

- FOUND 1/2" IRON AND WITNESSES BY WICKHAM. TRAVERSE OF SECTION 18 CONFORMED WITH BEARINGS AND DISTANCES BY WICKHAM. POSITION IS CONSISTANT WITH OCCUPATION EAST. ACCEPTED IRON BY WICKHAM AS A PROPER RESTORATION OF CORNER PROBABLY SET IN THE COURSE OF A SURVEY (NOT OF RECORD) MANY YEARS AGO.

ACT 345 BARRY COUNTY REMONUMENTATION APPROVED BY PEER REVIEW AT A MEETING HELD ON 1994 2 AUGUST

BRIAN REYNOLDS

COUNTY SURVEYOR

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD BARRY COUNTY REMONUMENTATION IRON (3/4"X36"W/ALUMINUM CAP)

FOUND NAIL IN NE SIDE OF A 10" HICKORY \$45E 18.76' FOUND NAIL IN NE SIDE OF AN 8" ASH N45W 28.22" SET 40d NAIL W/REMON TAG IN NW SIDE OF A 12" HICKORY N39E 38.32' SET 40d NAIL W/REMON TAG IN E SIDE OF AN 18" QUAD OAK N4W 87.62'

OFMICH BRIAN REYNOLDS LAND SURVEYOR NO. 31602 FOLANDS

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License