OCT 27 1994

acidMissich

## BARRY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

SEP 26 11 21 AM '94

	i mild i redame	sincin of mot 14, mion, 1.	· 1910					-				
For corners in					Sandry Schondelmaryer							
BARRY	Located in: 4N 8W	Corner Code <del></del>		REGISTER OF DEEDS								
(County)					n:	EG151	ENUF	DEED	)			
1. Public Land Survey	T R											
CARLTON TOWNSHIP	TR											
N 1/4 COR SECTION 18 T R				002220								
											2. Property Controlling S _	T R
in Section S	T R											
	T R		Re	aister	of De	eds S	tamp	& File	Numb	er		
	T R			<b>3.000</b>								
4. Lot No, Recorde				- А	8 (	c p	£ F	<b>в</b> н	ı j	KLM		
5. Private Claims			<del>,</del>				П					
				2  -	- 6 <del>-  </del>	<del></del> 5		<del> </del> −3−	2	1-1-		
				3 ├-	╂	<del></del>	$\vdash$	╂╌┼─	┼	1		
DOTAN DEVNOT BC	12 JUL	v 94	1	4 -		— ģ —	<del> </del>  -	<del> </del> 1¦0	<del> -</del> 1/1-	12		
I, BRIAN REYNOLDS, in a f	neid survey on	, 19	-:	5			<del>-   -</del>	┼-┼-	┼-	+		
do hereby certify that under requiremen	nts of P.A. 74, Michigan P.A.	of 1970, the corner points ment	oned n the	6	-18-	—1 <mark>7</mark>	1 <sub>6</sub>	15-	14-	<del> </del> 3		
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land							<u> </u>	<del>↓                                    </del>	<b>}</b>			
Management or by a decree of a Court of	of Law and/or that the corne	r points mentioned in lines 3, 4 a	and 5	8	-19	20	21	22_	<u> </u>	24		
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Court of Law; established, re-established, monumented, re-monumented, recovered, found						1_	Ш	$\perp \perp$				
Court of Law; established, re-estable expressed below:	lished, monumented, re-n	nonumented, recovered, toun	g as	10				1_27_		25_		
	all in the come town or	d range may be recorded		11	ĩ l	_Ĭ_						
NOTE: Not more than 4 corners,	, all in the same town an	id range, may be recorded		12		$\prod_{i=1}^{n}$		T [				
on this certificate.				13	-31	32 <del></del> -	-33	1 1	1 1	36		
A. Description of original monum	ient and accessories and	d/or subsequent restoration		13 [_			<del></del>	<del></del>				
			•									
1. GENERAL LAND OFFICE : SYLVES	STER SIBLEY D.S., DECEME	BER 1830.						oga (ANI)	ATLATINA	TIAN!		
A. MAPLE 8 S61E 78 A. HICKORY 2. COUNTY SURVEYOR NOTES: NO	NAME OR DATE (LIBER 1	OF SURVEYS, PAGE 273)	Α	CT 34	BAR	RY CO	UNIY	REMONU	⊏∡181€. \\A(Σ\!) \\	AHON HELD AN		
"TRON AND CROCKERY FOR	CORNER" BLACK ASH 1	0 S3 1/2W 83	APPR	OVED	BY PE	er rev	/IEW A	I A ME	LIING	HELD ON		
3 PRIVATE NOTES: BURT WICKHAM	/L, P.S. #17639, SURVEY OF	SECTION 18, c. 1992					•	Ba				
"FOUND 1/2" CAPPED REROD FLUSH WITH ROAD SURFACE" WITS: NAIL IN 24" MAPLE CLUSTER S10E 25.62'			2./	2 Aug. 94 DK  RRIAN REYNOLDS COUNTY SUR						HOVEVOS		
SOUTH END OF 48" OVAL CMP S10 W 34.30"			BRIA	n rey	IOLDS	•		COU	MII O	UNVLIO		
NORTH END OF 48" OVAL C	MP N15W 43.76'											
NAIL IN 8" ELM N60E 50.74 TREE LINE NORTH												
C/L BIT. ROAD NORTH 3.5'												
B. Description of corner evidence	e found and/or method a	applied in restoring or reest	ablishing	g come	er:							

FOUND 1/2" CAPPED IRON RECITED BY WICKHAM, IDENTIFICATION ON CAP OBLITERATED. SEARCHED EXTENSIVELY FOR IRON, CROCKERY, AND WITNESSES FROM COUNTY SURVEYOR NOTES, NOTHING FOUND. IT IS LIKELY THAT THE IRON AND CROCKERY WERE DESTROYED IN THE COURSE OF INSTALLING THE 48" OVAL CMP CULVERTAS RECITED BY WICKHAM.

ACCEPTED FOUND 1/2" IRON AS BEST AVAILABLE EVIDENCE OF CORNER POSITION.

REPLACED 1/2" IRON WITH STANDARD BARRY COUNTY REMONUMENTATION MONUMENT IN MONUMENT BOX

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

SET STANDARD BARRY COUNTY REMONUMENTATION IRON (3/4"X36" W/ALUMINUM CAP) AND INSTALLED MONUMENT BOX

SET 40d NAIL W/REMON TAG IN NW SIDE OF A 10" MAPLE S26W 41.17'
SET 40d NAIL W/REMON TAG IN NW SIDE OF A 4" MAPLE S46E 38.44'
FOUND 40d NAIL IN E SIDE OF A MAPLE CLUSTER S14E 25.70
FOUND 40d NAIL IN SW SIDE OF A MAPLE CLUSTER N40W 41.37
CORNER LIES 3.5' SOUTH OF C/L BITUMINOUS ROADWAY (SISSON ROAD)

Signed by 31602
Surveyor's Michigan License No. 31602

SEPT 23,

Date

BRIAN
REYNOLDS
LAND
SURVEYOR
NO.
31602

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975