SURVEY & REMONUMENTATION '

OCT 2 5 1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF BARRY RECEIVED FOR RECORD

Aug 18 8 00 AM '93

-	• <u></u>	
For corners barry	ın	۱.

5. Private Claims _

Corner Code ## Located In: (County) T 4M R 9W IRVING TWP.

Sandy Schondelmaryer REGISTER OF DEEDS

Sequence #1

.002076

Register of Deeds Stamp & File Number

1. Public Land Survey T _____ R __ T _____ R __ 2. Property Controlling ___ T ____ R __ in Section 3. Miscellaneous. Property in Sec.

__ , Recorded Plat _

Gary C. Bilow February 09, 1993 _ , in a field survey on _ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: F7: Post established by U. S. Deputy Surveyor S. Sibley in 1830 - accessories: White Oak 10 S4E 27 links and White Oak 12 M16-1/2W 24 links. County Surveyor Frank Bowen records in Volume 1 Page 271 in 1878 "East on random from Northwest corner 39.79 to 1/4 line - 38 N of post - found bearing - took new one: White Oak 30 N63E 28-1/2." County Surveyor L. Cobb records in 1890 records "Identified by stumps of both U.S. bearing trees and old stake. Set stone 24 x 10 x 7 with cross on top and earthen." Corner recorded under Act 74, PA 1970 by D. Bissell (PS \$18655) in 1983 as "Found 1/2" Pinched iron pipe - Replaced with 4" x 36" Conc. Mon. with Alum. Cap - accessories: N59W 24.01' Twin 18" R. Oak, N9E 31.38' 30" R. Oak, S73E 15.59' 10" Haple, and S7E 5.15' 10" Hickory."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: F7: Found MDNR monument and all of Bissell's witnesses. Did not accept. Found Stone set by Cobb in 1890 4.2' North. Accepted Stone as the best evidence of the original GLO post.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

F7: Left Stone in place - Set 1/2" x 24" rebar with plastic cap stamped "G.C. Bilow LLS 26453" on North side North 0.28', 1/2" capped rebar S27E 4.20', MDNR monument S65E 18.95', Nail & Tag in 10" Haple N17E 28.29', Nail & Tag in 30" Red Oak \$17E 9.28°, Nail & Tag in 10" Hickory N65W 20.63°, Nail & Tag in twin 18" Red Oak stump

5/6/93

1 License No. 26453

Surveyor's Michigan License No. .

OF MICHIGAN

GARY C BILOW PROFESSIONA

SURVEYOR No.

26453

OFESSION'S

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

10/26/93