## **Bay County Remonumentation**

MAR 2 6 1996

## LAND CORNER RECORDATION CERT. FICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in	
Bay (County) Located In: Corr	ner Code #
(County)	. 642 999° B.
1. Public Land Survey T 13N R 4E A	TEGORDE 356
·	
<u>T R</u>	TO R
T R	
T R	
2. Property Controlling S T R	003 244
in Section S T R	003 244 25 35
	Register of Deeds Stamp & File Number
Property in Section S T R	Tregister of Deeds Stainp & File Hulliber
•	
4. Lot No, Recorded Plat	
5. Private Claims	
<del>-</del>	2 6 5 4 3 2
	3
Croim M. Mal/ann	781011
Craig W. McVean , in a field survey on April 4	, 19 <u>95</u> , 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the	
in lines 1 and 2 above were in conformance with regulations and rules therefore	
manual of survey instructions of the United States Department of the	
Management or by a decree of a Court of Law and/or that the corner points n	
5 above were in conformance with the rules of the Michigan Board of Profe Decree of a Court of Law; established, re-established, monumented, re-monu	
as expressed below:	10 30 29 28 27 26 10 10 10 10 10 10 10 10 10 10 10 10 10
·	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 4 corners, all in the same town and range, may	be recorded
on this certificate.	12 31 32 33 34 35
	13
A. Description of original monument and accessories and/or subse	equent restoration:
A 1 - Intersect range line 28 Lks N of temp post - set post corner to	Unrecorded Survey - Edmands Engineering # MS-500, Section 6,
T13&14N, R3&4E - J. Wampler - 1822.	T13N, R4E - 1968.
Ironwood 10" S 69° E 19 Lks.	Recorded Surveys - Bay County - L. 794, P 46 - 3/8" re-rod - 1976;
Lynn 32" N 70° E 12 Lks.	L. 840, P. 588 - 3/8" iron - 1978.
Spicer Engineering Notes - 1/4" iron pin - 1961.	Recorded Surveys - Saginaw County - L. 1518, P. 252 - found 3/8" Iron - 1977.
Consumers Power Company Survey by Edmands Engineering -	ROIF- 1977.
Section 6, T13N, R4E and Section 1, T13N, R3E - set nail - 1968.	
, , , , , , , , , , , , , , , , , , , ,	
B. Description of corner evidence found and/or method applied in	restoring or reestablishing corner:
A 4 - Township corner common to T 42044N E22 4 E found	SIE 44 OAL /44 ABL BY 4 - 5 - The
A 1 - Township corner common to T 13&14N, R3& 4 E - found 3/8" x 18" rebar - down 0.6' per CPCo, unrecorded and recorded	NE 44.24' (44.15' - R) to face T.P. SE 42.15' (42.6' - R) to face U.P.
surveys. Rebar appears to be in agreement with Spicer	SE 42.61' (42.6' - R) to nail in E side U.P.
Engineering Notes per measurement of distances to E. Found	SW 41.0' (40.95' - R, 41.2' - R) to face U.P.
recorded witnesses as follows:	NW 63.8' (R & M) to SE corner block foundation building.
	Monument accepted as the best available evidence of the position
	of the originationner.
,	
4	ADDONES
	APPROVED LAND CORNER
	P.A. 345 OF 1990 - Bay County Date <u>3 A 0 0 5 5</u>
	MJM
	Michael MacDonald P.S.
	County Representative

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

 $\underline{A\ 1}$  - Replace 3/8" x 18" rebar with 2 1/2 " Bay County brass cap on 5/8" x 24' rebar in monument box.

N 44° E 44.60' to set nail and tag in NW side U.P.

N 44° E 44.60' to set nail and tag in NW side U.P.
N 42° W 63.80' to SE corner (Up 1') block foundation building.
S 33° E 42.56' to set nail and tag in NE side U.P.
S 47° W 41.30' to set nail and tag in NW side U.P.
N 58° W 103.49' to SW corner block foundation building.
S 30° W 176.45' to SE corner brick foundation (Up 1') of House #6012.

Surveyor's Michigan License No.

OFESSION P

ICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

OF MICHIGA

CRAIG W. MCVEAN PROFESSIONAL SURVEYOR No. 39088