SURVEY & REMONUMENTATION

APR 2 6 1995

BAY COUNTY REMONUMENTATION

LAND CORNER RECORDATION CERTIFICATE

_		RS	MI	00	OR	
Car	a a reliable #	W	WIL	ا في والآبر)	الإرسيان	ŧ

4. Lot No.

Private Claims

Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS CO

191

of Deeds Stamp & File Number

6

8

9

10

1.1

12

图 003

	(County)	Located In:	Corner Code ##	
1.	Public Land Survey	T 13N R 6E	L-5	
		T R		
		T R		
		T R		
2.	Property Controlling	S R		
	in Section	S T R		
3.	Miscellaneous	S T R		Register
	Property in Sec.	S T R		gister

Duane F. Ledy , in a field survey on . _June_23_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the

. Recorded Plat

current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
 - Set post at 40.29 chains from K-5, Orange Reisden, 1834 18" W. Maple N 22° W, 55 links S 3° E. 27 links 16" W. Oak Consumers Power Co. set 1/2" rerod with cap No. 18657, 1972 Edmands found 1/2" bar, 1993

Recorded Surveys

Consumers Power Co., Job No. 9052, 1972: L730 P380

Edmands Engineering, Job No. ELS 2052-13, 1993; L1257 P529

Others: L800 P347, L951 P404

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - Found rebar with cap <u>L-5</u>

Found recorded witnesses as follows:

S.W. 43.00' (43.0'R) to utility pole

N.W. 40.29' (40.29'R) to utility pole

Position of 1/2" rebar as measured and witnesses agree with position as shown on Consumers Power Co. survey.

Existing 1/2" rebar accepted as best evidence available of position of the original corner.

Accepted by Bay County Peer Review Group on August 25, 1994.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Replaced ½" rebar with 2¾" Bay County brass cap on 5/8" x 24" rebar in monument box. <u>L-5</u>

14.52' to nail an tag in guard rail post North N 45° W

40.40' to nail and tag in utility pole

S 45° W

12.18' to nail and tag in guard rail post

43.08' to nail and tag in utility pole

North

1' to centerline of Russell Road

West

12.00' to 1/2" rod at centerlines of Russell and Briggs Roads.

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 35/105, 97

MM Michael MacDonald P.S.

County Representative _ Date

Surveyor's Michigan License No.

21575

DUAL LED FROTESTA STATES OF MARD OF 1 FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197 REVISED MAY 14, 197

O DUANT