REMON CORNER D-7, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED

SECTION

4. Lot No.

For corners in		•
(County)	Located in:	Corner Code #
1. Public Land Survey	T <u>14N R 3E</u> T R T R	
2. Property Controlling in Section	STR STR	
Miscellaneous Property in Sec.	s	
4. Lot No, Recorded Pla	at	


1999 DEC 28 ₱ 1:01

Garden Tores Du Frence REGISTER OF DEEDS BAY COUNTY, MICHIGAN

Register of Deeds Stamp & File Number

5. Private Claims I, <u>Jerry L. Jones</u>, in a field survey on <u>June 18</u>, 1999, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the surrout manual of current instructions of the United States Paradactic States and the surrout manual of current instructions of the United States Paradactic States in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.



- A. Description of original monument and accessories and/or subsequent restoration:
- 1/2 Corner common to Sections 17 and 20 D-7

Survey by Glo, 1831, set post Survey by Edmands Engineering, 1972, 1983, found ½" pipe Survey by J. Schafer 1974, 1975, 1978, found ¾" pipe Survey by Wade-Trim, 1977, found 1/2" pipe LCRC by E. Goss, 1972, Found 1/2" pipe LCRC by K. Pomaville, 1999, found 1/2" pipe



- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- 14 Corner common to Sections 17 and 20 D-7

Found 1/2" rod and cap at position per surveys by Edmands Engineering, J. Schafer, Wade-Trim, and LCRC by K. Pomaville

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1/4 Corner common to Sections 17 and 20 D-7

Replaced rod with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in mon box; and is accepted as the best available evidence of the position of the accepted corner

S 60 Deg W, 155.00', nail and power pole (Rec. as 154.99') S 80 Deg W, 212.18', centerline top fire hydrant N 85 Deg E, 326.82', centerline top fire hydrant N 30 Deg W, 81.15', NE corner concrete drive South 37.66' to found nail in E/S 4" Twin Elm SSW 96.67' to NE corner of Garage #2257 NW 159.97' to SE Corner House

Signed by Surveyor's Michigan Liceuse No. 1982

Date 12/09/99
Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 9, 30, 77

Michael MacDonald P.S. County Broresent (