MAR 17 1999

Surveyor's Michigan License No. 19838

REMON. COR. D-13, WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P. A. 1970.

_	SECTION	Filing Re	equirement of Act 74, Mi	ch. P.A. 19	70	_	
For co	orners in			_	ro .	\mathbf{z}	
<u>Day</u>	(County)	Located in	n: Corner Code #		REGISTE AY COUN	1998 DEC	20
1. Pul	blic Land Survey	T <u>14N</u> R <u>3</u> TR_ TR_	E <u>D-13</u>		TROF	C-JA	RECORDED
in S 3. Mis	perty Controlling Section scellaneous sperty in Sec.	ST_R_ ST_R ST_R_ ST_R_		Registe	DEEDS VICHIGAN er of Deeds Stan	SP W	
4. Lot	No Boords	al Dias				•	
	No, Recorde /ate Claims	u riai			ABCD	D E C II	IJKLM
that und lines 1 a in the cu interior, corner p of the M	ler requirements of P.A. 74 and 2 above were in confo arrent manual of survey in Bureau of Land Managerr coints mentioned in lines a ichigan Board of Land Sur	on June 26, 1998, do herebe, Michigan P.A. of 1970, the ormance with regulations and estructions of the United Street or by a decree of a Cours, 4 and 5 above were in conveyors or by a Decree of a Coursed, found as expressed	corner points mentioned on rules therefore as required ates. Department of the art of Law and/or that the informance with the rules court of Law; re-established,	- 2 3 4 5 6 7 8 9	-65- -18- -78- -1817- -1920-	-43 91 161	01112- 51413-
NOTE:	Not more than 2 co	orners, all in the same t ertificate.	town and range, may be	10	-30-29- 31-32-	 	
A. Des	scription of original mo	onument and accessorie	es and/or subsequent res	12		<u> </u>	########
D-13	South 1/4 corner Section					STATE	OF MICHIGA
		et 1" rod in mon box hittier 1968, found mon box ineering 1974, 1975, found m	non box			Lioensed Su	FESSIONAL POR NO. 19838
WITNE	SS NOTE: Witnesses presented	from above surveys an	d LCRC's are available in tee and is on file at the Re	dossler file;	; which was eds Office.	POF	ESSION A
B. Des			thod applied in restoring o				
D-13	South 1/4 corner Section						
	Found 1" rod 30" long in	mon box (dug 3' found nothi	ng) per surveys by MDOT, Hun	ter and Whittie	er, Edmands Enc	nineering and	LCRC by L. McGinnis
Corner			at a Peer Review Committ				
C. Des			ories established to perpet			n of the cor	ner:
D-13	South 1/4 corner Section			•			
	Found 1" rod in mon box brass cap stamped Bay C	per surveys by MDOT, Hunte County Remonumentation PS	or and Whittier, Edmands Engli 19838 and is accepted as the	neering, and L best available	.CRC by L. McGi evidence of the	innis; replaced position of the	d rod with 5/8" rod an accepted corner.
	Northeast 43.52' to south S 45 Deg E, 19.34', pk nai	wast corner of west concrete il in top guardrail post	post of south guardrail (Rec. as post of north guardrail (Rec. as	43.5) 43.5)			
	S 40 Deg W, 19.06', pk na				APPROVED LAND	CORNER	
	N 50 Deg W, 25.19', pk na N 50 Deg E, 22.50', pk nai				P.A. 345 OF 1990 Date <u>24 Sept</u>	- Bay County	
	East 40.7', West edge of overpass bridge				MJM'		
	Saginaw Co. corner not fo	ound			Michael MacDonal County Represent		
Signed I	by 0	-10-	n n	ate	17/11	100	
-		70.			you	170	

004

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971 141 Revised Jan., 1983