MAR 1 7 1999

SURVEY & REMONDENCE TRANSPORT

REMON. COR. H-11 WILLIAMS TWP. LAND CORNER RECORDATION CERTIFICATE

	SECTION	Filing Requir	rement of Act 74, Mich	. P.A. 1970		
_	rners in			•	E.	
Bay	(County)	Located in:	Corner Code #	BAYU	REG	7998 n
1. Pub	olic Land Survey	T <u>14N</u> R <u>3E</u> T R T R	<u>H-11</u>	1 5	E &	RECORDED
in S 3. Mis	perty Controlling ection cellaneous perty in Sec.	S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R R S T		Register of Deeds	EDS 6	
4. Lot 5. Priv	No, Recorded rate Claims	Plat		ABC	DEFO	HIJKLM
that und lines 1 a in the cu interior, corner p of the M	ler requirements of P.A. 74, I and 2 above were in conform arrent manual of survey ins Bureau of Land Manageme points mentioned in lines 3, ichigan Board of Land Surve	n July 14, 1998, do hereby certiful Michigan P.A. of 1970, the corner nance with regulations and rules structions of the United States and or by a decree of a Court of 4 and 5 above were in conformations or by a Decree of a Court by a Decree of a Court by the court of the court	or points mentioned on therefore as required Department of the Law and/or that the mance with the rules of Law; re-established,	2 -6 - 3 + 4 -7 - 5 + 6 - 18 - 7 - 8 - 19 - 9 + 10 - 30 - 30 - 10	-54- -89- -1716- -2021-	-101112- -151413- -222324-
NOTE:	Not more than 2 cor recorded on this cer	ners, all in the same tow tificate.	n and range, may be	11	-29 -32 -32 -33-	-27-26-25- -34-35-36-
A. Description of original monument and accessories and/or subsequent restoration:						
H-11	1/4 corner common to Se	ctions 27 and 34			A ST	E OF MICHIGAN
	Survey by Glo, Harvey Par Survey by Edmands Engir Hunter-Whittier records in	neering 1983, 1987, 1988			# * /	JONES PROFESSIONAL SURVEYOR No.
WITNE		from above surveys and Li to peer review committee			ras e.	19838 SS
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:						
H-11	11 1/4 corner common to Sections 27 and 34					
Found 3/8" rod at location per surveys by Edmands Engineering and Hunter-Whittier records						
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:						
H-11	1/4 corner common to Se	ctions 27 and 34				
	Found 3/8" rod per surveys by Edmands Engineering, removed rod, dug 3', found 3/8" rod 2' deep, replaced rods with 5/8" rod and brass cap stamped Bay County Remonumentation PS 19838 in mon box; and is accepted as the best available evidence of the position of the accepted corner.					
	S 45 Deg W, 42.69', pk nai N 40 Deg W, 42.38', pk nai S 35 Deg W, 71.9', centerli N 80 Deg E, 222.30', nail a South 1', centerline Salzbu East 7', center Saunders R	il in power pole, Rec. 42.1 ine 6" Spruce and BC disc in power pole arg Road			Donald P.S.	nty
Signed	by Ja	ung f. On	<u></u>	ate <u>/2/</u>	101/9	3
Surveyor's Michigan License No. 19838 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971						

004

150

Revised Jan., 1983