SURVEY & REMONUMENTATION

APR 2 3 1998

Surveyor's Michigan License No. 19838

REMON COR. M-7, WILLIAMS TWP LAND CORNER RECORDATION CERTIFICATE

SECTION	Filing Require	Filing Requirement of Act 74, Mich. P.A. 1970				
Bay		Cowney Code #		~ .	E	
(County)	Located in:	Corner Code #		SS #	5 2	
Public Land Survey	T <u>14N</u> R <u>3E</u> T <u>14N</u> R <u>4E</u> T R T R	M-7 A-7		SE S	RECORDED	
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R		Register of Deeds Sta	EDS & File Nur	S D D D D D D D D D D D D D D D D D D D	
4. Lot No. , Record	ed Plat					
5. Private Claims			A B C D	E F G	ніјкьм	
that under requirements of P.A. 7 lines 1 and 2 above were in conf in the current manual of survey interior, Bureau of Land Manage corner points mentioned in lines of the Michigan Board of Land St monumented, re-monumented, re-NOTE: Not more than 2 crecorded on this of A. Description of original managements.	vey on July 15, 19 97, do hereby of 4, Michigan P.A. of 1970, the corner ormance with regulations and rules instructions of the United States ment or by a decree of a Court of 3, 4 and 5 above were in conformativeyors or by a Decree of a Court of ecovered, found as expressed belowers, all in the same town certificate. The conformation of the c	r points mentioned on therefore as required Department of the Law and/or that the nance with the rules of Law; re-established, w: n and range, may be and/or subsequent resto	9	7-16	$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$	
M-7/4-7 Corner common to Sec	ctions 13 and 14, T14N-R3E & 18 an	ld 19, T14N-R4E				
Survey by P. Ciosek, 1 Survey by D. Burgin, 1	339, set post, J. Mullett 984, found iron, L-962, P-725 986, 1992, found 1/2" iron, L-1035, , 1987, found iron, L-1062, P-460	P-507 and L-1307, P-932			SERRY L.	
WITNESS NOTE: Witnesse present	es from above surveys and Le ed to peer review committee	CRC's are available in d and is on file at the Reg	lossier file; which was jister of Deeds Office		JONES 1	
B. Description of corner e	vidence found and/or method	d applied in restoring or	reestablishing corne	Pr:	No. 19838	
M-7/4-7 Corner common to Se	ctions 13 and 14, T14N-R3E & 18 ar	nd 19, T14N-R4E			A OFESSION PLANT	
Found 1/2" rod with st	ones around per surveys by P. Cios	ek, D. Burgin and L. McGinn	is		The Company	
C. Description of monume	ent for corner and accessorie	s established to perpetu	uate locating the pos	ition of the o	corner:	
M-7/A-7 Corner common to Se	ctions 13 and 14, T14N-R3E & 18 ar	nd 19, T14N-R4E				
Found 1/2" rod, replace Ciosek, D. Burgin and	ced 1/2" rod with 5/8" rod and brass L. McGinnis and is accepted as the	s cap stamped Bay County R best available evidence of th	Remonumentation PS 198 he position of the accepte	38 in mon box ed corner.	a, per surveys by ₽.	
N 45 Deg E, 103.2', SV N 25 Deg E, 114.70', c	e top telephone box (R) V corner house #4489 (R) enter line top hydrant (R) all and disc in power pole (R) of 8 Mile Road		P.A. 345 OF Date <u>-2 7</u>	TM Donald P.S.	nty	

图 094

Revised May 14, 1971 Revised Jan., 1983

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Date _

17