SURVEY & REMONUMENTATION

APR 2 3 1998

REMON COR. M-8, WILLIAMS TWP

SECTION For corners in Bay		rement of Act 74, Mic		BAXE S	<u>S</u>	
(County)	Located in:	Comer Code #		S S S	5	22
1. Public Land Survey	T <u>14N</u> R <u>3E</u> T <u>14N</u> R <u>4E</u> TR TR	M-8 A-8		The Allow NTY. MICHIG	7 29 M	RECORDED
 Property Controlling in Section Miscellaneous Property in Sec. 	S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R S T R R S T R S T R S T R S T R S T R S T R S T R S T R T R		Register of Deeds	Stamp & File	97 Number	
4. Lot No, Recorded 5. Private Claims	Plat		ABC	DEF	GHI	JKLM
I, <u>JERRY L. JONES</u> , in a field survey that under requirements of P.A. 74, lines 1 and 2 above were in conform	Michigan P.A. of 1970, the corn	er points mentioned on	2 -6 3 -1 4 -7	54 -89	3	-11-12-

in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

6 7 8 19 9 10 30 28 26 11 12 13

OF MICHIGAN

ERRY L

JONES

PROFESSIONAL

SURVEYOR

No.

19838

OFESSION P

A. Description of original monument and accessories and/or subsequent restoration:

M-8/4-S Corner common to Sections 24, T14N-R3E and 19, T14N-R4E

Government survey, set post, 1830's Edmands Engineering, found mon box 1971, 1976, 1984, 1987, L-664, P-195 and L-799, P-268 and L-1177, P-22 and L-1062, P-460 and L-1402, P-185 Wade-Trim, found "T" iron in mon box, 1991, 1996

Burgin Land Surveys, found "T" iron in mon box, 1992, L-1307, P-932 LCRC, L. McGinnis, found "T" iron in mon box, 1992, L-003, P-08

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-8/4-5 Corner common to Sections 24, T14N-R3E and 19, T14N-R4E

Found "T" iron in mon box per surveys by Edmands Engineering, Wade-Trim, Burgin Land Surveys, and LCRC by L. McGinnis

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-8/A-G Corner common to Sections 24, T14N-R3E and 19, T14N-R4E

Found "T" iron in mon box, replaced iron with 5/8" rod and brass cap stamped, Bay County Remonumentation PS 19838, per survey by Edmands Engineering, Wade-Trim, Burgin Land Surveys, and LCRC by L. McGinnis in mon box and is accepted as the best available evidence of the position of the accepted corner.

S 40 Deg E, 48.08', center line top hydrant (R) S 40 Deg W, 58.08', nail in power pole (R) N 45 Deg W, 62.52', nail in power pole (R) N 50 Deg E, 43.87', nail in power pole (R)

APPROVED LAND CORNER MJM

Michael MacDonald P.S. County Representative

Date

10/22/97

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971 Revised May 14, 1971

Revised Jan., 1983



Signed by

Surveyor's Michigan License No. 19838