SURVEY & REMONUMENTATION

APR 2 3 1998

REMON COR. M-6, WILLIAMS TWP LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corne TON Bay	99		1 *	=		,
(County)	Located in:	Corner Code #	® RE.	1 1 1 1 1 1 1 1 1 1		
Public Land Survey	T <u>14N</u> R <u>3E</u> T <u>14N</u> R <u>4E</u> TR	M-6 A-6	GUNTY, MI	7 29	RECORDED	
Property Controlling in Section	STR		CHIGAN	16. WW	Ð	
Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp		oer	
4. Lot No, Recorded	d Plat					
5. Private Claims			ABCDE	FGH	IJ	KLM
i, <u>JERRY L. JONES</u> , in a field surver that under requirements of P.A. 74, lines 1 and 2 above were in conformation. In the current manual of survey in interior, Bureau of Land Management	Michigan P.A. of 1970, the corne mance with regulations and rules estructions of the United States	r points mentioned on therefore as required Department of the	2 -65- 3	$-\overline{1}+\overline{1}$	0-11-	12-

7

8

9 10

11

12

13

31

29

2

28

3 3

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules

of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established,

A. Description of original monument and accessories and/or subsequent restoration:

M-6/A-6 Corner common to Sections 13, T14N-R3E and 18, T14N-R4E

monumented, re-monumented, recovered, found as expressed below:

Government survey, 1839, J. Mullett, set wood post Survey by L. McGinnis, 1972, Found 3/8" bent rod, L 691, P 597

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-6/A-6 Corner common to Sections 13, T14N-R3E and 18, T14N-R4E

Found 3/8" rod 4" long, top bent in loop with stones around, per survey by L. McGinnis



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-6/A-6Corner common to Sections 13, T14N-R3E and 18, T14N-R4E

Found 3/8" rod, top bent in loop, replaced rod with 5/8" rod and brass cap stamped, Bay County Remonumentation PS 19838 in mon box, per survey by L. McGinnis and is accepted as the best available evidence of the position of the accepted corner.

N 50 Deg E, 226.10', SW corner of pole building
N 15 Deg E, 198.85', nail and Bay County disc in power pole
S 60 Deg W, 54.84', nail in power pole (R)
N 5 Deg E, 374.96', center line top hydrant
East 12', center line 8 Mile Road

APPROVED LAND CORNER
P.A. 345 OF 1990 - Bay County
Date 37 Tune 57

Michael MacDonald P.S.
County Representative

Signed by	$\mathcal{O}_{\mathcal{A}}$	ecer	70	rusa

Surveyor's Michigan License No. 19838

Date 10/22/97

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971