Bay County Remonumentation

Eor	corners in		R RECORDATION CERT			10 M	Jun 25		
I-OI	Bav	Located In:	Corner Code #					771	
	(County)						က	FILED	
1.	Public Land Survey	T 14N R 4E T R T R T R	C 11			DEEDS.	35 III 35	Ö	
2.	Property Controlling in Section	S T R				003	198	8	
3.	Miscellaneous	S T R		Donies	tor of Do	ada Ctama	o ella M	umbar	
	Property in Section S T R R				ister of Deeds Stamp & File Number				
		Recorded Plat			A B	c p e e	<u> </u>		<u> </u>
5.	Private Claims			·····	2 6-		_ _		. {
					3	8 - 9			
, (Craig W. McVean	, in a field survey on April	5 19 9	5	5		- 		1
do in l ma Ma Ma 5 6 De	hereby certify that under rec lines 1 and 2 above were in c anual of survey instruction anagement or by a decree of above were in conformance	quirements of P.A. 74, Michigan P.A. conformance with regulations and russ of the United States Department of a Court of Law and/or that the cole with the rules of the Michigan Boablished, re-established, monument	of 1970, the corner points me ales therefore as required in the ent of the Interior, Bureau of the points mentioned in lines of ard of Professional Surveyors	entioned courrent of Land 3, 4 and or by a	6 18 7 8 19 - 9 10 30 - 30 - 10	20-29-2		-23	24
	•	orners, all in the same town and	range, may be recorded		11	 		 	╌┼╼┄┥
145	on this certificate.	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,			12 31	323	334	-35	36
Α.	Description of original	monument and accessories a	nd/or subsequent restorati	ion:	1311		<u> </u>	<u> </u>	_1
	C 11 Set Post - Ransse Beech 12" S 62-1/2° E 46 DO. 6" N 34° W 35 Lks.		L. 735, P. 5 L. 769, P. 9	319 - 1971; L. (520 - 1974; L. 7 55 - 1975; L. 77 65 - 1993; L. 13	'35, P <i>.</i> 52(77, P. 176	6 - 1974; L. 1 6 - 1975; L. 8	749, P. 531	- 1974;	
	quadrants. C.P.Co. Witness Sheet - L.C.R.C L. 1, P. 61 - mo L.C.R.C L. 1, P. 347 - fo L.C.R.C L. 2, P. 349 - m	- monument box - 1960 with ang monument box and Witnesses. nument box - DeLaMater - 1971. ound monument box - Goss - 1972. onument box - McGinnis - 1977. 56, P. 162 - found monument box -	les in 4					•	
3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:									
	C 11 Found 1/2" x 1.5' kg	ong Iron rod driven into 1" O.D. x	1.5' Iron			-	MANAGE.	•.₹. \.	

C 11 Found ½" x 1.5' long iron rod driven into 1" O.D. x 1.5' iron pipe in monument box per B.C.R.C., C.P.Co., L.C.R.C.'s and recorded surveys. Found recorded Witnesses as follows:

S 4.1' (4' - R) to physical centerline Salzburg Rd.

N 20° W (R) 94.93' (94.85' - R) to face U.P.

S 30° W (R) 67.93' (67.9' - R) to Pk in P.P.

N 45° E (R) 39.75' (39.8' - R) to Pk in guy pole.

Monument accepted as the best available evidence of the position of the original corner.



). Description of monument for corner and accessories established to perpetuate locating the position of the corner:

C 11 Replace from rod and pipe with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in monument box.

N 16° W 95.24' to nail and tag in E side U.P.

N 51° W 117.02' to SE corner brick siding on House #491.

S 35° W 67.77' to nail and tag in SE side U.P.

N 48° E 45.33' to centerline stem FH

S 23° E 138.63' to NW'ly corner block foundation of House #508.

igned by Oracia M. Millean	Date 6-26-95
iurveyor's Michigan License No. 39088	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975