Bay County Remonumentation

		ER RECORDATION CERTIF		23		
For corners in		ement of Act 74, Mich. P.A	. 1970	2003 YAB 2003 2003 2003 2003 2003 2003 2003 2003	25	
Bay (County)	Located In:	Corner Code #		点点 (
1. Public Land Survey	T 14N R 4E T R T R				FILED S 36 M 195	
Property Controlling in Section Miscellaneous	S T R S T R			(ii)3	200	
Property in Section		1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Register of De	eds Stamp	& File Number	
f. Cralg W. McVean I. do hereby certify that under recipion lines 1 and 2 above were in commanual of survey instruction Management or by a decree of 5 above were in conformance Decree of a Court of Law; este as expressed below: NOTE: Not more than 4 coordinate.	, in a field survey on	A. of 1970, the corner points menti- rules therefore as required in the cu- ment of the Interior, Bureau of corner points mentioned in lines 3, 4 goard of Professional Surveyors or inted, re-monumented, recovered, for d range, may be recorded	2 - 6 - 3 3 - 4 - 7 - 1 10ned 6 - 18 - 18 - 19 - 18 4 and 8 - 19 - 19 10 - 30 - 11 12 - 31 - 13	C D E F	10 11 12 12 13 14 13 14 13 14 14 13 14 14 14 14 14 14 14 14 14 14 14 14 14	M
E 11 Set Post - J. Mullet Beech 10" S 65° W 27 Lk DO 12" S 85° E 54 Lks. B.C.R.C. Witness Book - 1959. L.C.R.C L. 1, P. 61 - fc L.C.R.C L.1, P. 383 - 4"	t, 1840. s. 4" iron in pavement. Set monu ound monument box - DeLaMate	1971; L. 654, 1972; L. 684, 1975; L. 759, F ment box box - 1981; L P. 125 - 1987; er - 1971.	s: <u>veys</u> - L. 652, P. 315 - f P. 211 - 1971; L. 654, P. 245 - 1972; L. 707, P. 53 - 1975; L. 904, P. 2 . 993, P. 752 - found r L. 1159, P. 119 - 1990;	P. 229 - 1971 P. 465 - 1973 23 - found Pk allroad spike	; L. 676, P. 478 - l; L. 754, P. 486 - over monument - 1985; L. 1042,	

3. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E11 Found railroad spike at road surface - Excavate below railroad spike and find monument box down 0.85'. Find 3/4" iron rod in box down 1.4'. Also found Pk nall during excavation. Monuments as called for by B.C.R.C., L.C.R.C.'s and record surveys. Found recorded Witness as follows: SE 95.45' (95.6' - R) to face U.P. NE 62.5' (R & M) to centerline U.P. SW 82.05' (82.1' - R) to centerline U.P. 3/4" Iron rod in monument box accepted as the bord available evidence of the position of the original corner.



2. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E11 Leave 3/4" iron rod in monument box in place and raise to surface with 2-3/4" Bay County brass cap on 5/8" x 24" rebar in monument box.

S 82° E 3.96' to centerline monument box - no Iron.

S 22° E 96.23' to nail and tag in E side U.P.

S 25° W 82.16' to nail and tag in W side U.P.

N 73° E 62.50' to nall and tag in S side U.P.

N 25° W 107.01' to SE corner brick siding on House #995.

N 58° E 69.93' to nail and tag in NW side 3" Pine.

APPROVED LAND CORNER P.A. 345 OF 1990 - Bay County Date 18 1990 - Bay County Michael MacDonald P.S. County Representative

igned by Orang W. Ma Vean	Date 6-26-95
urveyor's Michigan License No. 39088	FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 29, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983