Bay County Remonumentation

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	raing nequireme	ant Of Act 74, Milett.	.A. 1010			
Bay	Located In:	Corner Code #	,		_	
(County)				10 10		
				REI BAY		
1. Public Land Survey	T 14N R 4E	113	1	COURT	22	נכ
	T R		1	\$ \tau \ \	4	RECORDED
	T R				း ယ	O _R
	T R		ĺ	3 3	US.	Đ
	ST R		003	255 副	<u> </u>	Ð
	ST R		"	200 C		
	T R		Registr	er of Deeds Sta	ımp & File	Number
Property in Section S	S T R				p « 1 110	
4. Lot No, Recor	rdad Dlat					
5. Private Claims, Recor	ded Plat			A B C D E	F G H	1 J K 1
5. Private Claims				2 - 6 5		
				3		+
				4	_	
Craig W. McVean in a	field survey onApril 5	19	95	5		
do hereby certify that under requirer	nents of P.A. 74. Michigan P.A. of	1970, the corner points m	entioned	6 18 -17		1/1/1
in lines 1 and 2 above were in confor	rmance with regulations and rules	therefore as required in th	e current			
manual of survey instructions of	the United States Department	of the Interior, Bureau	of Land			
Management or by a decree of a Co 5 above were in conformance with	ourt of Law and/or that the corner	of Professional Surveyors	3,4 and	8 20 20	-2122	23 2
Decree of a Court of Law; establish	ed, re-established, monumented.	re-monumented, recovered	ed, found	9	111	+++
as expressed below:	·			10 30 29	-2827-	26 2
NOTE: Not more than 4 corners	s, all in the same town and rar	ige, may be recorded		1 #		
on this certificate.				12 31 32	-3334	35-3
				13		
A. Description of original mon	nument and accessories and/	or subsequent restorat	ion:			
	on 34 and 35 - J. Mullett - 1839.			P. 247 - found mo		_
No date.	ilon Witness Book - Witnesse Witness Sheet - Monument box	es -	670 - 1988; L. 13	115, P. 761 - 1994		
B. Description of corner evide	ence found and/or method ap	oplied in restoring or re	establishing co	rner:		
R4E - found 1/2" Iron rod In road - down 0.3' - in agreemer 1/2" x 27" long iron rebar and driven between 2" - 6" diame	common to Section 34 and 35, T monument box at N edge black it with recorded surveys. Remo old monument box - found rod ter timbers lying flat and aligne is the best available evidence of	ktop oved was ed N	P.A. 345 OF Date <u>79</u> <u>M.J.</u>			
			Michael Ma County Rep	cDonald P.S. resentative		
	•	,	county riep			- 1
C. Description of monument t	for corner and accessories es	stablished to perpetuat	e locating the p		Section of the	MA.
149 Bankanal 4/00 090 to	rohan and manipulant have with A	4/3"		1E	OF MICH	10 M
	rebar and monument box with 2 ' x 24" rebar in monument box.	114		SARTE		N. A.
				# 4 € ``	MAICE AS	148
	o and R; 35.25' - B.C.R.C.) to fo	ound		% ™ !	MCVEAN	
chiseled "X" on W end 60" RG S 60° W 79.38' (79.35' R & M to	SP. → R.R. spike) to set nail and tag in	NW	٠	PR PR	OFESCION/ SURVEYOR	AL SU
side U.P.	_	-		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Ma.	
E 31.56' to capped 3/8" rebar.				LICE REBOR	39088	
S 30° E 31.87' to capped 3/8"	rendf.				OFESSION	AL STATE
				A STATE OF THE PARTY OF THE PAR	VFE SSION	No.
<i>a</i> · · ·	11/ 00.01		,	/	- add to the state of the state	
Signed by Cruy A Surveyor's Michigan License N	V. The Vear	Dat	e /2/19/	195		
	39020			AM STATE DOARD OF PRO-	ECCIONAL CURVE	ODE IAN OR 4044
Surveyor's Michigan License N	0. 21000	FOR	IM APPHOVED BY MICHIG	AN STATE BOARD OF PROF	RE	VISED MAY 14, 1975
						REVISED JAN., 1983